




2022-05-18 MBK 525L Hydraulic Oil

GN reference #: 2022-192

Please find the following information as a follow up to the Spill report submitted May 18, 2022 by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-MEA1530, Part H, Item 8c.

Spill Description

During operations at Meadowbank, a hydraulic hose of the container handler failed causing a total of 525L of hydraulic oil to leak on the warehouse sea cans storage pad.



Spill location: 65°01'07.83"N 96°04'09.78"W


There were no off-site impacts or discharges to any receiving watercourses. Distance to the closest lake is 400m to Third Portage Lake

Cause of Spill

Hydraulic hose failure

Remediation Actions

The operator immediately shut down the equipment and called the environment department. A combination of absorbent booms and peat moss were placed around the equipment to capture as much oil as possible. The used spill response material was disposed appropriately at the Hazmat facility and approximately 8m3 of contaminated soil was brought to the Meadowbank landfarm.



Corrective measures

A routine visual inspection of all systems is performed during pre-operation checks as a part of the preventative maintenance program.

Closure

We trust that the above details described appropriately the spill incident that occurred at the Meadowbank site on May 18, 2022 and the cleanup activities. Please contact the undersigned should you have any questions.



Samuel Tapp | Environment Coordinator

samuel.tapp@agnicoeagle.com | Direct 819.759.3555 x4606744 |

Agnico Eagle Mines Limited - Meadowbank Division, Suite 540 - Baker Lake, Nunavut, Canada X0C 0A0

agnicoeagle.com    

Sent from Meadowbank