



## 2023-11-22 MBK 15L Sewage Water

GN reference #: 2023-503

Please find the following information as a follow up to the Spill report submitted November 23<sup>th</sup>, 2023, by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-MEA1530, Part H, Item 8c.

### Spill Description

During a visual inspection of the gymnasium lift station (lift station 12), the sewage piping leading into the building was found to be leaking. As a result of the leak, approximately 15L of sewage water was spilled onto the frozen ground.



Spill Location: 65° 1'18.91"N 96° 4'12.62"W on IOL

There were no off-site impacts or discharges. Distance to the closest water body is 320 m to Third Portage Lake.

### Cause of Spill

The failure of the sewage pipe was a consequence of the regular wear and the forceful winds of a blizzard.

## Remediation Actions

A plumber was called to identify the source and fix the pipe. Approximately 1m<sup>3</sup> of contaminated material was collected and brought to the Tailing Storage Facility at Meadowbank.



## Corrective measures

The plumber repaired the damaged pipe after its discovery. A monthly visual inspection of the sewage infrastructure is implemented to identify any signs of wear and prevent potential spills.

## Closure

We trust that the above details described appropriately the spill incident that occurred at the Meadowbank site on November 22<sup>th</sup>, 2023, and the cleanup activities. Please contact the undersigned should you have any questions.



**Samuel Tapp** | Environment Coordinator

[samuel.tapp@agnicoeagle.com](mailto:samuel.tapp@agnicoeagle.com) | Direct 819.759.3555 x4606744 |

Agnico Eagle Mines Limited - Meadowbank Division, Suite 540 - Baker Lake, Nunavut, Canada X0C 0A0

[agnicoeagle.com](http://agnicoeagle.com)     

Sent from Amaruq