

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS



NT-NU 24-HOUR SPILL REPORT LINE

Tel: (867) 920-8130 • Email: spills@gov.nt.ca

A	Report Date:	13	9	24	Report Time:	3:30 pm	<input checked="" type="checkbox"/> Original Spill Report OR <input type="checkbox"/> Update # _____ to the Original Spill Report	Report Number:
	Occurrence Date:	13	9	24	Occurrence Time:	12:30 am		
C	Land Use Permit Number (if applicable):				Water Licence Number (if applicable): NWB-2AM-MEA1530			
D	Geographic Place Name or Distance and Direction from the Named Location: MEADOWBANK COMPLEX						Region: <input type="checkbox"/> NT <input checked="" type="checkbox"/> Nunavut <input type="checkbox"/> Trans-boundary or Ocean	
E	Latitude:				Longitude:			
	65	0	56	Seconds	96	3	51	Seconds
F	Responsible Party or Vessel Name: AGNICO EAGLE MINES LTD				Responsible Party Address or Office Location: BAKER LAKE X0C 0A0 PO.540			
G	Any Contractor Involved: ARCTIC FUEL SERVICES LTD.				Contractor Address or Office Location: Baker Lake P.O. Box 350			
H	Product Spilled: <input type="checkbox"/> Potential Spill DIESEL FUEL				Quantity in Litres, Kilograms or Cubic Metres: 1000L		U.N. Number:	
I	Spill Source: Fuel Truck				Spill Cause: Human Error		Area of Contamination in Square Metres: 80m2	
J	Factors Affecting Spill or Recovery:				Describe Any Assistance Required:		Hazards to Persons, Property or Environment:	
K	Summary of the spill incident and efforts / description of the incident: A fuel tanker was overfilled during the refueling process at the Meadowbank fuel farm, resulting in approximately 1000 liters of diesel fuel spilling onto the ground. Spill response materials were deployed, and heavy equipment was brought to the scene to contain the spill. Approximately 20 cubic meters of contaminated material was collected into a roll-off container and transported to the Meadowbank landfarm. There were no off site impacts or discharges. Distance to the closest water body is 290m to Third Portage Lake Spill Location: Northing 65' 0' 56.69" Easting 96' 3' 51.08" (on IOL) Contact information: Felix Quessy 819-759-3555 EXT.: 4606744							
L	Reported to Spill Line by: Felix Quessy		Position: Env. Lead Technician		Employer: Agnico Eagle Mines		Location Calling From: Meadowbank	
							Telephone: (819) 759-3555	
M	Any Alternate Contact: Robin Allard		Position: Env. Gen. Supervisor		Employer: Agnico Eagle Mines		Alternate Contact Location: Meadowbank	
							Alternate Telephone: (819) 860-1414	

REPORT LINE USE ONLY

N	Received at Spill Line by:	Position:	Employer:	Location Called:	Report Line Number:
	Lead Agency: <input type="checkbox"/> EC <input type="checkbox"/> CCG/TCMSS <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> CIRNAC <input type="checkbox"/> CER <input type="checkbox"/> Other: _____	File Status: <input checked="" type="checkbox"/> Open <input type="checkbox"/> Closed			
	Agency:	Contact Name:	Contact Time:	Remarks:	
	Lead Agency:				
	First Support Agency:				
	Second Support Agency:				
	Third Support Agency:				