



## 2024-09-13 MBK 1000L Diesel

GN reference #: 2024-356

Please find the following information as a follow up to the Spill report submitted September 13, 2024 by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-MEA1530, Part H, Item 8c.

### Spill Description

A fuel tanker was overfilled during the refueling process at the Meadowbank fuel farm, resulting in approximately 1000 liters of diesel fuel spilling onto the ground.



Spill location: 65' 0' 56.69" 96' 3' 51.08"


There were no off-site impacts or discharge to any receiving watercourses. Distance to the closest water body is 290 meters to Third Portage Lake.

## Cause of Spill

Human error

## Remediation Actions

Spill response materials were deployed, and heavy equipment was brought to the scene to contain the spill. Approximately 20 cubic meters of contaminated material was collected into a roll-off container and transported to the Meadowbank landfarm.



## Corrective measures

An investigation into the root causes of the spill was completed. The procedural aspects of the task and the mechanical system are being reviewed to identify any potential deficiencies. Additionally, the installation of an engineered system to prevent similar events from recurring is being evaluated.

## Closure

We trust that the above details described appropriately the spill incident that occurred at the Meadowbank site on September 13, 2024 and the cleanup activities. Please contact the undersigned should you have any questions.



**Samuel Tapp** | Environment Coordinator

[samuel.tapp@agnicoeagle.com](mailto:samuel.tapp@agnicoeagle.com) | Direct 819.759.3555 x4606744 |

Agnico Eagle Mines Limited - Meadowbank Division, Suite 540 - Baker Lake, Nunavut, Canada X0C 0A0

[agnicoeagle.com](http://agnicoeagle.com)     

Sent from Amarug