



## 2025-03-06 MBK 300L Hydraulic Oil– Hyster

GN reference #: 2025-119

Please find the following information as a follow up to the Spill report submitted March 6th, 2025, by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector as requested; as due diligence and without prejudice by Agnico Eagle Mines Ltd. and in accordance with the conditions under the Nunavut Water Board License 2AM-MEA1530, Part H, Item 8c.

### Spill Description

During operations at Meadowbank, Hyster TPA03 was parked and idling at the EMR Yard in between shifts. When arriving to the location the employee noticed a hydraulic oil spill under the equipment.



Spill location(s): 65° 3'13.27"N 96° 5'29.55"W

The spill was within the Operations footprint of Meadowbank. There were no off-site impacts or discharges. Distance to the closest water body is ~190m to Unnamed Lake.

### Cause of Spill

Mechanical Failure

## Remediation Actions

The contaminated materials were segregated then collected and brought to the appropriate Hazmat Disposal Facilities.



## Corrective measures

TPA03 was towed to the maintenance shop for repair, damaged hydraulic lines were replaced, and the unit was assessed. A review of pre-operational checks and idling procedure was completed with warehouse crews.

## Closure

We trust that the above details described appropriately the spill incident that occurred at the Meadowbank site on March 6th, 2025, and the cleanup activities. Please contact the undersigned should you have any questions.



**Tom Thomson** | Environmental Coordinator

tom.thomson@agnicoeagle.com | Direct 819.759.3555 | 4606744

Agnico Eagle Mines Limited - Meadowbank Division, Suite 540 - Baker Lake, Nunavut, Canada X0C 0A0

[agnicoeagle.com](http://agnicoeagle.com)     

Sent from Meadowbank