



## APPENDIX A5

### Operation Landfill



*Photograph 69: Operation Landfill, Overview of Interior of Facility from East Corner (20 September 2017)*



*Photograph 70: Operation Landfill, Crest and Interior Slope of Northeast Berm, Looking Southeast (20 September 2017)*





## APPENDIX A5

### Operation Landfill



*Photograph 71: Operation Landfill, Exterior Slope of Northwest Berm Looking East from West Corner (20 September 2017)*



*Photograph 72: Operation Landfill, Exterior Slope of Northwest Berm, and Looking West from East Corner (20 September 2017)*





## APPENDIX A5

### Operation Landfill



*Photograph 73: Operation Landfill, Exterior Slope of Northeast Berm, and Looking Southeast from North Corner (20 September 2017)*



*Photograph 74: Operation Landfill, Exterior Slope of Northeast Berm, and Looking Northwest from East Corner (20 September 2017)*





## APPENDIX A5

### Operation Landfill



*Photograph 75: Operation Landfill, Exterior Slope of Southeast Berm Looking Northeast from South Corner (20 September 2017)*





## APPENDIX A5

### Operation Landfill



*Photograph 76: Operation Landfill, Exterior Slope of Southwest Berm, Looking Northwest from South Corner. Some Water Ponded Outside the Landfill Adjacent to the Access Ramp (20 September 2017)*

\\golder.gds\gal\burnaby\final\2016\3 proj\1660296 agnico\_provide engineering s\_nunavu\1660296-024-r-rev0-3000\appendix a\A5\9. operation landfill appendix.docx





# **APPENDIX A 6**

**Exploration Camp Pad and Access Road, Fresh Water Intake,  
Diffuser Access, Fuel Storage, and Landfarm**





## APPENDIX A6

### Exploration Camp and Access Road



*Photograph 1: Overview of Exploration Camp Pad and Access Road. Google Earth Image (August 2017)*



*Photograph 2: Exploration Camp Pad, North Slope, and Looking West, near Fresh Water Intake Access Road (21 September 2017)*





## APPENDIX A6

### Exploration Camp and Access Road



*Photograph 3: Exploration Camp Pad, South Slope, Looking West from East End (21 September 2017)*



*Photograph 4: Exploration Camp Pad, Erosion on South Slope (21 September 2017)*





## APPENDIX A6

### Exploration Camp and Access Road



*Photograph 5: Exploration Camp Pad, Localized Ponding and Erosion on South Slope (21 September 2017)*



*Photograph 6: Exploration Camp Pad, South Slope Looking North. Water Treatment Discharge on Left (21 September 2017)*





## APPENDIX A6

### Exploration Camp and Access Road



*Photograph 7: Exploration Camp Pad, Slope South of Camp Trailers, Looking Southwest (21 September 2017)*



*Photograph 8: Exploration Camp Pad, Fuel Storage Tanks near Helicopter Pad (21 September 2017)*





## APPENDIX A6

### Exploration Camp and Access Road



*Photograph 9: Exploration Camp Pad, Interior Slope Looking South (21 September 2017)*



*Photograph 10: Exploration Camp Fresh Water Intake Access, Looking Northeast (21 September 2017)*





## APPENDIX A6

### Exploration Camp and Access Road



*Photograph 11: Exploration Camp Fresh Water Intake Access, Looking Northwest (21 September 2017)*



*Photograph 12: Exploration Camp Fresh Water Intake Access, Culvert for Pipe Crossing (21 September 2017)*





## APPENDIX A6

### Exploration Camp and Access Road



*Photograph 13: Exploration Camp Fresh Water Intake Pump House (21 September 2017)*



*Photograph 14: Exploration Camp Pad. Diffuser Access Road Adjacent to Camp Trailers, Looking Northeast (21 September 2017)*





## APPENDIX A6

### Exploration Camp and Access Road



*Photograph 15: Exploration Camp Diffuser Access Road, near Camp, Looking Northwest (21 September 2017)*



*Photograph 16: Exploration Camp Diffuser Access Road, Some Cracking along Slope, Looking Northwest (21 September 2017)*





## APPENDIX A6

### Exploration Camp and Access Road



*Photograph 17: Exploration Camp Diffuser Access Road, Looking Northwest (21 September 2017)*



*Photograph 18: Exploration Camp Diffuser Access Road, cracking near Southeast end near Meliadine Lake (21 September 2017)*