



APPENDIX A6

Exploration Camp and Access Road



Photograph 19: Exploration Camp Diffuser Access Road, Adjacent to Meliadine Lake, Looking South (21 September 2017)



Photograph 20: Exploration Camp Diffuser Access Road, Adjacent to Meliadine Lake, Looking North (21 September 2017)



APPENDIX A6

Exploration Camp and Access Road



Photograph 21: Exploration Camp Access Road, Downstream ends of Culverts near Camp (black corrugated plastic and corrugated steel) (22 September 2017)



Photograph 22: Exploration Camp Access Road, Downstream end of Culvert near Camp (22 September 2017)



APPENDIX A6

Exploration Camp and Access Road



Photograph 23: Exploration Camp Access Road, Downstream end of Culvert near Camp (21 September 2017)



Photograph 24: Exploration Camp Access Road, Upstream end of Culvert near Camp (21 September 2017)



APPENDIX A6

Exploration Camp and Access Road



Photograph 25: Exploration Camp Access Road, Upstream end of Culvert near Fuel Storage (22 September 2017)



Photograph 26: Exploration Camp Access Road, Downstream end of Culver near Fuel Storage, Partially Blocked (21 September 2017)



APPENDIX A6

Exploration Camp and Access Road



Photograph 27: Exploration Camp Access Road, Water Ponded Along East Edge of Road between Fuel Storage and Intersection with Main Road (21 September 2017)



Photograph 28: Exploration Fuel Storage Pad, North Slope, Looking South (19 September 2017)



APPENDIX A6

Exploration Camp and Access Road



Photograph 29: Exploration Fuel Storage Pad, East Slope, Looking North (19 September 2017)



Photograph 30: Exploration Fuel Storage Pad, Cracking along Crest of East Slope, Looking South (19 September 2017)



APPENDIX A6

Exploration Camp and Access Road



Photograph 31: Exploration Fuel Storage Pad, Minor Cracking near Crest of East Slope, Looking North (19 September 2017)



Photograph 32: Exploration Fuel Storage Pad, Looking Northwest (19 September 2017)



APPENDIX A6

Exploration Camp and Access Road



Photograph 33: Exploration Camp Landfarm, Downstream Face of West Slope, Looking Northwest (19 September 2017)



Photograph 34: Exploration Camp Landfarm, Small Pond of Water at Toe of Northeast Corner, Possible Seepage (19 September 2017)



APPENDIX A6

Exploration Camp and Access Road



Photograph 35: Exploration Camp Landfarm, North Slope and Crest, Looking Northeast (19 September 2017)



Photograph 36: Exploration Camp Landfarm, West Slope Crest, Looking Southeast. Water Poned within Landfarm (19 September 2017)



APPENDIX A6

Exploration Camp and Access Road



Photograph 37: Exploration Camp Landfarm, East Slope, Looking Southeast (19 September 2017)



Photograph 38: Exploration Camp Landfarm, South Slope and Crest, Looking Southwest (19 September 2017)



APPENDIX A6

Exploration Camp and Access Road



Photograph 39: Core Storage Pad, West Slope Looking North (19 September 2017)



Photograph 40: Core Storage Pad, Cracking on Crest of East Slope, Looking South (19 September 2017)

\\golder.gds\gal\burnaby\final\2016\3 proj\1660296 agnico_provide engineering s_nunavu\1660296-024-r-rev0-3000\appendix a\A6\exploration camp appendix.docx



APPENDIX B

Meliadine All-Weather Access Road (AWAR) Inspection Photographs



APPENDIX B

Meliadine AWAR Inspection – 2017



Photographs 1 to 4
were taken at
KM14.7 at access
road to B12 Quarry

Photograph 1: At KM14.7, Access Road to B12 Quarry. Upstream End of 500 mm \varnothing Corrugated HDPE Culvert. Some Ponding Against Quarry Access Road and AWAR below Inlet of Culvert (20 September 2017)



Photograph 2: View through Culvert Under Access Road to B12 Quarry at KM14.7, Some Dents, No Flow, Small Amount of Ponded Water Within Culvert (20 September 2017)



APPENDIX B

Meliadine AWAR Inspection – 2017



Photograph 3: Downstream End of Culvert through Access Road to B12 Quarry at KM14.7 (20 September 2017)



Photograph 4: Water Pooled Adjacent to AWAR and Access Road to B12 Quarry at KM14.7. Looking at AWAR from Quarry Access Road. (20 September 2017)