



Photo 50: Top Liner punctured by excavator while placing Type C material; Station 1+040



Photo 51: Patch completed on punctured Top Liner at Station 1+040



Photo 52: Coletanche ES3 liner panels in a shipping/storage sea can



Photo 53: Deformed Coletanche ES3 liner panel pulled out of shipping/storage sea can



Photo 54: Excessive wrinkling on Liner Panels 62 to 66



Photo 55: Finalizing Patches R4, R5 and R6