



Photo 56 Water ponding at under liner hinge point
View at Station 1+390



Photo 57: Water breach over Type H upstream material on working platform
View from Station 1+400 facing down chainage



Photo 58: View of completed Dike D-CP1 from Station 1+585 facing downstream side



Photo 59: View of completed Dike D-CP1 from Station 1+585 facing upstream side