PHOTOGRAPHS

Photo 1	Pushing lake ice, snow, boulders, and cobbles to construct working platform
Photo 2	Placing first lift of Type A material (working platform) on the upstream side
Photo 3	Compaction of first lift of Type A material on the upstream working platform
Photo 4	Key trench excavation between Stations 0+210 and 0+290
Photo 5	Key trench sloping and hammering
Photo 6	Key trench – bedrock encountered at ~1.4 m depth below original ground surface
Photo 7	Final dental cleaning on key trench bottom prior to placing Type F material
Photo 8	Type F material placement
Photo 9	Type F material placement and compaction
Photo 10	Placing first lift of upstream fillet Type F material
Photo 11	Compacting a lift of Type C upstream fillet
Photo 12	Placing downstream fillet Type F material
Photo 13	Excavator placing first lift of Type C material over liner on upstream slope
Photo 14	Placing and spreading a lift of Type B material around Station 0+200
Photo 15	Placing Type C below liner bedding material on dike upstream slope at Station 1+240
Photo 16	Placing and compacting Type B crest material
Photo 17	Placing Type A material; view from Station 1+040
Photo 18	Placing Type A thermal cover around Station 1+320
Photo 19	Deploying a Phase 1 liner panel
Photo 20	Placed Phase 1 liner
Photo 21	Completed Phase 2 liner at Station 1+050
Photo 22	Phase 2 liner placement at Station 1+100
Photo 23	PVC Pipe housing HGTC-1 lying on first lift of Type C material over bottom liner
Photo 24	PVC pipe housing HGTC-2 lying on first lift of Type C material over bottom liner
Photo 25	Drilling hole to install VGTC-3
Photo 26	Taking readings from HGTC-2
Photo 27	Survey Monument M2 to be installed
Photo 28	Survey Monument M2 installation
Photo 29	Looking at Survey Monument M1, protective casing painted orange
Photo 30	Densometer test on a lift of Type C fillet material around Station 0+025
Photo 31	QC monitoring the mixing of Bentonite-Augmented (Type F) material
Photo 32	Type F material swell test
Photo 33	Densometer and Sand Cone Tests on Type F fillet material around Station 0+095
Photo 34	Coring key trench base to take a jar test sample at depth of 2.3 m from OG at Station 0+245



Photo 35	Jar Test #26 – frozen sample
Photo 36	Jar Test #26 – thawed sample
Photo 37	Performing a tensile resistance test on a liner welding pre-qualification test strip
Photo 38	Performing an ultra-sonic test on a seam between two liner panels
Photo 39	Destructive test sample location between Panels 35 and 36
Photo 40	Water ponding downstream, afternoon of May 13, 2017, view from Station 1+200
Photo 41	Removal of saturated Type F under liner at hinge point, approximate Station 1+210
Photo 42	Area of water behind liner, Type F over liner at hinge point, Station 1+190
Photo 43	Ponding water downstream, morning of May 15, 2017, view from Station 1+090
Photo 44	Downstream toe on May 16, 2017 high water line down, Station 1+100
Photo 45	Downstream side of dike on May 18, 2018 showing low water level
Photo 46	D-CP5 overview of upstream side from Station 1+020 facing up chainage





Photo 1: Pushing Lake Ice, snow, boulders and cobbles from dike's footprint to construct working platform (first lifts of dike's shell)

View from Station 1+300 facing down chainage



Photo 2: Placing first lift of Type A material (working platform) on the upstream side View from Station 1+280 facing up chainage





Photo 3: Compaction of first lift of Type A material on the upstream working platform View from Station 1+090 facing up chainage



Photo 4: Key trench excavation between Stations 0+210 and 0+290





Photo 5: Key trench sloping and hammering View from Station 0+190 facing up chainage



Photo 6: Key trench - bedrock encountered at ~1.4 m depth below original ground surface Between Stations 0+040 and 0+060





Photo 7: Final dental cleaning on key trench bottom prior to placing Type F material View from Station 0+30 facing up chainage



Photo 8: Type F material placement View from Station 0+155 facing down chainage



Photo 9: Type F material placement and compaction View from Station 0+180 facing up chainage



Photo 10: Placing first lift of upstream fillet Type F material View from Station 0+100 facing down chainage

