



Photo 21: Completed Phase 2 liner
View from 1+050 facing up
chainage



Photo 22: Phase 2 liner placement
View from Station 1+100 facing down
chainage



Photo 23: PVC Pipe housing HGTC-1 lying on first lift of Type C material over bottom liner
View from Station 0+004 facing up chainage)



Photo 24: PVC pipe housing HGTC-2 lying on first lift of Type C material over bottom liner
View from Station 0+298 facing down chainage



Photo 25: Drilling hole to install VGTC-3
View from Station 1+195 facing down chainage



Photo 26: Taking readings from HGTC-2




Photo 27: Survey Monument M2 to be installed



Photo 28: Survey Monument M2 installation