



Photo 39: Destructive test sample location between Panels 35 and 36



Photo 40: Water ponding downstream, afternoon of May 13, 2017
View from Station 1+200 facing down chainage



Photo 41: Removal of saturated Type F under liner at hinge point
Approximate Station 1+210 facing up chainage



Photo 42: Area of water behind liner—granular material is Type F over liner at hinge point
Approximate Station 1+190