

2025-07-30 WTM 200L Diesel Fuel

GN reference #: 2025-329

Please find the following information as a follow up to the Spill report submitted July 31st, 2025, by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-WTP1830, Part H, Item 8c.

Spill Description

During operations at the Whale Tail Mine, a haul truck was offloading material at the Whale Tail rock facility when a dozer attempted to assist by lifting the truck box using the corner of its blade. During this maneuver, the dozer blade struck and damaged the fuel tank's wigging attachment, resulting in a diesel spill of approximately 200 liters onto the pad surface. The spill occurred within an active deposition area.



Spill Location: 65°24'30.02"N 96°42'59.04"W (on IOL)

The spill remained within the mine operations footprint. There were no off-site impacts or discharges. Distance to the closest water body is ≈700m to Kangislulik

Cause of Spill

Human error

Remediation Actions

A heavy equipment unit was immediately deployed to scrape and remove the affected area. All contaminated material was collected and transported to the Whale Tail Landfarm for proper disposal.



Corrective measures

The incident will be reviewed with all operators to reinforce the importance of adhering to established procedures and authorized practices. Additionally, an investigation is underway in collaboration with the Health and Safety department to identify and implement best practices moving forward.

Closure

We trust that the above details described appropriately the spill incident that occurred at the Whale Tail site on July 30th, 2025, and the cleanup activities. Please contact the undersigned should you have any questions.



Samuel Tapp | Environment Coordinator samuel.tapp@agnicoeagle.com | Direct 819.759.3555 x4606744 | Agnico Eagle Mines Limited - Meadowbank Division, Suite 540 - Baker Lake, Nunavut, Canada X0C 0A0