


Appendix G

Monitoring water quality stations

Meliadine Interim Closure and Reclamation Plan – Update 2020		Original -V.03
2021/04/07	674942-4000-4EER-0002	Technical Report



LEGEND

- CATCHMENT BOUNDARY
- SERVICE ROAD
- HAUL ROAD
- WATERBODY
- WATER COLLECTION POND
- DRAINED POND AREA
- OPEN PIT
- OVERBURDEN
- WASTE ROCK
- ORE
- TAILINGS
- INDUSTRIAL SITE PAD
- REGULATED MONITORING LOCATION
- GENERAL AQUATIC MONITORING LOCATION
- VERIFICATION MONITORING LOCATION



L'INFORMATION CI-CONTENUE EST LA PROPRIÉTÉ DE AGNICO EAGLE LTD. ET DOIT ÊTRE RETENUE SANS AUTORISATION ÉCRITE PRÉALABLE.
TOUTE TRANSMISSION DE COPIES À AUTRUI ET TOUTE UTILISATION AUTRE QUE CELLE POUR LAQUELLE L'INFORMATION EST PRÉVUE SONT INTERDITES.
© AGNICO EAGLE LTD.

THE INFORMATION HERE ON IS THE PROPERTY OF AGNICO EAGLE LTD. AND MUST BE RETURNED UPON REQUEST.
WITHOUT WRITTEN PERMISSION, ANY COPYING TRANSMITTAL, TO
OTHERS AND ANY USE EXCEPT THAT FOR WHICH IT IS LOANED ARE PROHIBITED.
© AGNICO EAGLE LTD.

—	—
—	—
—	—
—	—
—	—
—	—
TITRE / TITLE	# DWG

DESSINS EN RÉFÉRENCE/REFERENCE DRAWINGS

REV	DESCRIPTION	DATE	PAR BY

REVISIONS

DESSINÉ PAR DRAWN BY	DATE
VÉRIFIÉ PAR CHECKED BY	
APPROUVÉ PAR APPROVED BY	
No. PROJET PROJECT NO.	6526
DATE	

TITRE / TITLE
AGNICO EAGLE – MELIADINE GOLD PROJECT
MONITORING LOCATIONS DURING OPERATIONS
FOR WATER MANAGEMENT

ECHELLE/ SCALE	1:15000	FICHIER FILE	.DWG	REVISION	0	FEUILLE/SHT 1 / 1
No. DESSIN/ DRAWING NO.						

Figure 7: Water Quality Monitoring Locations at Itivia



Note – MEL-12 is located to the Northwest along the Bypass road but could not be effectively included in this map due to its distance from Itivia.

(AEM, 2020c)

Figure 3. EEM Receiving Environment Sampling Locations

