
LOCATION AND CROSSING DESCRIPTION

Site ID: CV-110-3 **Dates Surveyed:** 01-Jul-19 Waterbody Type: Pond **Project Interaction:** Rail Pond Infilling + Culvert **Centreline UTM Coordinates:** 17W 561445 E 7912240 N Culvert Length (m): 30 5 Number of Barrels: Culvert Diameter/Span (mm): 1200 Slope (%):

GENERAL PHYSICAL CHARACTERISTICS

Surface Area (m²): 2,469 Shoreline Length (m): 314 Drainage Basin Area (m²): 0.132

Maximum Depth (m): 0.5 (estimated) Mean Depth (m): -





SUMMARY

The rail loop will infill a portion of a shallow (approximate maximum depth 0.5 m), marshy pond in two locations (CV-110-3 and CV-110-2). The pond is isolated and not connected to any other waterbodies, including nearby Sheardown Lake. The pond lacks clearly defined inflows and outflows and is not fish habitat.



BARRIERS

Upstream/	UTM		Barrier Type		Height	Gradient	Description	Site	
Downstream	Easting	Northing	1	2	3	(m)	(°)	Description	Label
Inflowing Stream	g Stream All inflows appear to be diffuse over terrestrial habitat and not fish-bearing								
Outflowing Stream	All outflows appear to be diffuse over terrestrial habitat and not fish-bearing								


FISH HABITAT POTENTIAL

Nearest Potential Overwintering Habitat - ARCH: N/A Distance to Nearest Potential Overwintering Habitat - ARCH (km): N/A

Overwintering Habitat Upstream of Site - ARCH (Y/N): N/A

Species	Spawning	Overwintering	Rearing	Adults Present
ARCH	N	N	N	N
NNST	N	N	N	N

FISHING SITES



FISHERIES DATA

Date: 01-Jul-19 Temperature (°C): NR Gear Used: Backpack Electrofisher/Visual

Distance Fished (m): NR Duration Fished (seconds): 165

Species	Season	Effort (Seconds)	Fish Captured	Fish Observed	CPUE (No. Fish/60 Seconds)	Length Range (mm)
ARCH	Spring	165	0	0	-	-
NNST	Spring	165	0	0	-	-


INFILL HABITAT

Area	Fines (%)	Gravel (%)	Small Cobble (%)	Large Cobble (%)	Boulders (%)
Nearshore	100	0	0	0	0
Offshore	100	0	0	0	0

OTHER NOTES/OBSERVATIONS

Electrofishing was limited to areas of the pond near site CV-110-3 that were sufficiently deep enough for electrofisher use. There was no clear outflow or connectivity to the west towards an adjacent pond. The area between the ponds was a series of isolated shallow pools among vegetation with no clear passage or flow in spring 2019. There was some connectivity to adjacent pools at the time of the survey.

01-JUL-19



Photos 1. Photos of the pond infilled at CV-110-3: (A) at the infill site looking east; (B) at the infill site looking west; (C) at the infill site looking north across the pond; (D) looking west towards distant unconnected ponds; (E) eastern end of CV-110-2/110-3 marshy pond complex; and (F) terrain west of CV-110-2/110-3.