LOCATION AND CROSSING DESCRIPTION

Site ID: CV-102-7a **Dates Surveyed:** 20-Jun-19 Waterbody Type: Pond **Centreline UTM Coordinates:** Rail Pond Infilling 17W 557379 E 7915248 N Culvert Length (m): **Project Interaction:** N/A Number of Barrels: N/A Culvert Diameter/Span (mm): Slope (%): N/A


GENERAL PHYSICAL CHARACTERISTICS

Surface Area (m²): 205 Shoreline Length (m): 54 Drainage Basin Area (m²): 0.410

Maximum Depth (m): 0.5 (estimated)

Mean Depth (m): -





SUMMARY

The rail will infill a shallow (approximate maximum depth 0.5 m) pond at site CV-102-7a. During the spring 2019 survey, both the inflow and outflow had areas of subsurface flow and the pond was largely isolated. With higher water levels the pond may connect 20 m downstream to the CV-102-7b infill area. The entire pond has fine substrate with some aquatic and flooded terrestrial vegetation.

There is a permanent vertical drop barrier 50 m downstream of the pond at the confluence with the stream crossed by CV-103-1 which prevents fish access. This pond does not provide fish habitat.

BAFFINLAND IRON MINES MARY RIVER PROJECT




FISH HABITAT:

ARCTIC CHAR - NO NINESPINE STICKLEBACK - NO

BARRIERS

Upstream/	UTM		Barrier Type		Height Gradie	Gradient	Description	Site	
Downstream	Easting	Northing	1	2	3	(m)	(°)	Description	Label
Downstream	557423	7915224	VD	SHALL		0.5	12	Permanent Barrier: Vertical drop at downstream confluence	Α





Δ

FISH HABITAT POTENTIAL

Nearest Potential Overwintering Habitat - ARCH:

Camp Lake

Distance to Nearest Potential Overwintering Habitat - ARCH (km):

~0.37

Overwintering Habitat Upstream of Site - ARCH (Y/N):

No

Species	Spawning	Overwintering	Rearing	Adults Present
ARCH	N	N	N	N
NNST	N	N	N	N

FISHERIES DATA

Date:

20-Jun-19

Temperature (°C):

NR

Gear Used:

Visual

Distance Fished (m):

N/A

Duration Fished (seconds):

N/A

CDIE Length Pange

	Species	Season	Effort (Seconds)	Fish Captured	Fish Observed	CPUE (No. Fish/60 Seconds)	Length Range (mm)
	ARCH	Spring	N/A	0	0	-	-
I	NNST	Spring	N/A	0	0	-	-

ENCROACHMENT HABITAT

Area	Fines (%)	Gravel (%)	Small Cobble (%)	Large Cobble (%)	Boulders (%)	
Nearshore	100	0	0	0	0	
Offshore	100	0	0	0	0	

OTHER NOTES/OBSERVATIONS

No fish were observed in the entire pond in spring 2019 (visibility extended to the bottom of the pond). The pond is likely frequently isolated and there is a permanent downstream vertical barrier to upstream fish passage. Due to the barrier, this pond does not provide fish habitat.

20-JUN-19



Photos 1. Photos of the pond in spring: (A) looking northeast; (B) looking north; and (C) looking southeast.