
#### LOCATION AND CROSSING DESCRIPTION

Site ID:	CV-8-1	Dates Surveyed:	16-Jun-19	Waterbody Type:	Stream
Project Interaction:	Rail Culvert	Centreline UTM Coordinates:	17W 508304 E 7969709 N	Culvert Length (m):	38
Number of Barrels:	1	Culvert Diameter/Span (mm):	1200	Slope (%):	5

#### GENERAL PHYSICAL CHARACTERISTICS

Flow Regime: Intermittent Stream Order: 1 Drainage Basin Area (km²): 0.007





### **SUMMARY**

The North Rail crosses an unnamed intermittent stream at CV-8-1. The stream drains southwest towards the existing Tote Road where it flows into a roadside ditch that diverts water towards a pond to the northwest and eventually a culvert crossings at CV-154. There are no existing culverts at CV-152 or CV-153. There was very little water present in spring 2019.

The drainage ditch is steep with some patches of subsurface flow under cobble, but the stream is also located on a hill with a high gradient that acts as a natural permanent barrier to upstream fish passage. The site is not connected to upstream overwintering habitat.

There is no fish habitat at CV-8-1.

BAFFINLAND IRON MINES MARY RIVER PROJECT




FISH HABITAT:

ARCTIC CHAR - NO NINESPINE STICKLEBACK - NO

## BARRIERS

Upstream/	n/ UTM		Barrier Type		Height Gra	Gradient	Description		
Downstream	Easting	Northing	1	2	3	(m)	(°)	Description	
Downstream	508307	7969715	HG				>10	Permanent Barrier: High gradient across the entire survey reach ranging from 9–12 $^{\circ}$	Α





### FISH HABITAT POTENTIAL

Nearest Potential Overwintering Habitat - ARCH: N/A Distance to Nearest Potential Overwintering Habitat - ARCH (km): N/A

Overwintering Habitat Upstream of Site - ARCH (Y/N): No

Species	Spawning	Overwintering	Rearing	Adults Present
ARCH	N	N	N	N
NNST	N	N	N	N

### FISHERIES DATA

Date: 16-Jun-19 Temperature (°C): NR Gear Used: Visual


Distance Fished (m ): N/A Duration Fished (seconds): N/A

Species	Season	Effort (Seconds)	Fish Captured	Fish Observed	CPUE (No. Fish/60 Seconds)	Length Range (mm)
ARCH	Spring	N/A	N/A	0	-	-
NNST	Spring	N/A	N/A	0	-	-

### COMMENTS

This stream does not connect to fish-bearing waters on its downstream end, and any upstream fish passage is blocked by a high gradient from the roadside ditch to the crossing. There is no fish habitat at this crossing.

16-JUN-19



**Photos 1.** Photos taken at the crossing centreline in spring (A) facing upstream; (B) facing downstream; and (C) across (right bank looking at left bank).