

Technical Report Geotechnical Site Inspections	Revision		
	#	Date	Page
Report No.: 630212-0000-000-4GER-0001	00	2015-09-10	B-1

Appendix B – PHOTO COLLAGE OF THE INSPECTIONS (selected photos)



Photo 1: A view of the Crusher Pad base post a rainfall event (muddy surface)



Photo 2: A view of the Crusher Pad expansion adjacent to an existing natrual water course (potential for interferences with water course during an extreme flood)



Photo 3: A view of the Crusher Pad expansion and its associated surface runoff drain



Photo 4: A view of the Crusher Ore Stocpile expansion and its toe drain





Photo 5: A view of the Sedimentation Pond associated with the Crusher Pad area at Mine Site



Photo 6: A view of the Emergency Spillway, Intake Channel to Sedimentation Pond and perimeter dam raising in progress associated with the Crusher Pad Area at Mine Site





Photo 7: A view of the exposed liner on PSPW ponds at Mine Site



Photo 8: A close-up view of the exposed liner and embankment conditions of PSPW ponds at Mine Site





Photo 9: A view of the mine Hazardous Waste and Environment Containment Systems and its Embankment/Berm at Mine Site (typical)



Photo 10: A view of the Mine Hazardous Waste and Environmental Containment systems (typical) at Mine Site





Photo 11: A view of the mine site Landfill site - progressive cover placement



Photo 12: A view of the mine site Landfill side slope and vicinity (typical) and the planned fencing layout in the background (flag posts)



Photo 13: A view of the mine site Sewage Effluent Discharge Point station



Photo 14: A view of the mine site Sewage Effluent Discharge Area meeting with the Mary River



Photo 15: A view of the Mine Waste Rock Storage Facility and its associated runoff collection pond




Photo 16: A view of the Mine Waste Rock Storage Facility collection pond liner and embankment/berm





Photo 17: A view of the Mine Waste Rock Storage Facility Pond and Water Treatment Facility (dome in the background)



Photo 18: A view of the Mine Waste Rock Storage associated Water Treatment Facility



Photo 19: A view of the Mine Waste Rock Storage Facility's Post Water Treatment Settling/Polishing Pond Embankment/Berm



Photo 20: A view of the Mine Waste Rock Storage Facility's Post Water Treatment Sedimentation Arrangements and Pond



Photo 21: A view of the mine site Bulk Fuel Storage Facility - Base



Photo 22: A view of the mine site Bulk Fuel Storage Facility – Perimeter Embankment