



Photograph E2-25 Bridges 7 – km 32+300

Date: September 1, 2018

Photo Number: 347

Description: Looking at the north abutment from upstream.



Photograph E2-26 Bridges 7 – km 32+300

Date: September 1, 2018

Photo Number: 346

Description: Looking at the north abutment from downstream.



Photograph E2-27 Bridges 7 – km 32+300

Date: September 1, 2018

Photo Number: 345

Description: Looking at the south abutment from upstream.



Photograph E2-28 Bridges 7 – km 32+300

Date: September 1, 2018

Photo Number: 344

Description: Looking at the south abutment from downstream.



Photograph E2-29 Bridges 8 – km 43+500

Date: September 1, 2018

Photo Number: 342

Description: Looking at the north abutment.



Photograph E2-30 Bridges 8 – km 43+500

Date: September 1, 2018

Photo Number: 343

Description: Looking at the south abutment.



Photograph E2-31 Bridges 9 – km 44+800

Date: September 1, 2018

Photo Number: 340

Description: Looking at the north abutment.



Photograph E2-32 Bridges 9 – km 44+800

Date: September 1, 2018

Photo Number: 341

Description: Looking at the south abutment.

APPENDIX F

Amaruq Road Photographic Log

APPENDIX F1

Quarries along the AWPR
Photographic Log



Photograph F1-1: Quarry 1 – km 5+200

Date: August 28, 2018

Photo Number: 028

Description: View of south and east walls.



Photograph F1-2: Quarry 1 – km 5+200

Date: August 28, 2018

Photo Number: 029

Description: View of south wall.



Photograph F1-3: Quarry 2 – km 13+250

Date: August 28, 2018

Photo Number: 039

Description: View of north and west walls.



Photograph F1-4: Quarry 2 – km 13+250

Date: August 28, 2018

Photo Number: 064

Description: View of north and east walls.



Photograph F1-5: Quarry 3 – km 23+700

Date: August 28, 2018

Photo Number: 047

Description: View of east wall.



Photograph F1-6: Quarry 3 – km 23+700

Date: August 28, 2018

Photo Number: 048

Description: View of west wall. Presence of loose rock along steep wall.



Photograph F1-7: Quarry 5 – km 34+650

Date: August 28, 2018

Photo Number: 052

Description: View of north and east walls.



Photograph F1-8: Quarry 5 – km 34+650

Date: August 28, 2018

Photo Number: 051

Description: View of north and west walls.



Photograph F1-9: Quarry 6 – km 36+470

Date: August 28, 2018

Photo Number: 054

Description: View of south and west walls.



Photograph F1-10: Quarry 6 – km 36+470

Date: August 28, 2018

Photo Number: 053

Description: View of south and east walls.



Photograph F1-11: Quarry 8 – km 42+950

Date: August 28, 2018

Photo Number: 057

Description: View of south wall. Presence of loose blocks.



Photograph F1-12: Quarry 8 – km 42+950

Date: August 28, 2018

Photo Number: 058

Description: View of west wall.



Photograph F1-13: Quarry 9 – km 44+600

Date: August 28, 2018

Photo Number: 059

Description: View of west and south walls. Presence of loose blocks at the base of the wall.



Photograph F1-14: Quarry 9 – km 44+600

Date: August 28, 2018

Photo Number: 060

Description: View of north and east walls. View of a pile of loose material.



Photograph F1-15: Quarry 10 – km 48+900

Date: August 28, 2018

Photo Number: 061

Description: View of the west wall. Presence of unstable blocks.



Photograph F1-16: Quarry 10 – km 48+900

Date: August 28, 2018

Photo Number: 062

Description: Overview of the quarry looking north at the east and north walls.



Photograph F1-17: Quarry 11 – km 53+500

Date: August 28, 2018

Photo Number: 063

Description: Overview of Quarry 11 looking at the west and north walls.



Photograph F1-18: Quarry 11 – km 53+500

Date: August 28, 2018

Photo Number: 064

Description: Overview of Quarry 11 looking at the north and east walls.



Photograph F1-19: Quarry 12 – km 58+300

Date: August 28, 2018

Photo Number: 065

Description: View of the south and east walls.



Photograph F1-20: Quarry 12 – km 58+300

Date: August 28, 2018

Photo Number: 066

Description: View of the west wall.



Photograph F1-21: Quarry 13 – km 62+350

Date: August 28, 2018

Photo Number: 070

Description: View of the west and north walls.



Photograph F1-22: Quarry 13 – km 62+350

Date: August 28, 2018

Photo Number: 069

Description: Looking at the south and east walls.



Photograph F1-23: Quarry 14 – km 65+700

Date: August 28, 2018

Photo Number: 071

Description: View of west and south walls. Quarry flooded.



Photograph F1-24: Quarry 14 – km 65+700

Date: August 28, 2018

Photo Number: 072

Description: View of north and west walls. Quarry flooded.



Photograph F1-25: Quarry 15 – km 67+600

Date: August 28, 2018

Photo Number: 073

Description: View of the south and west walls.



Photograph F1-26: Quarry 15 – km 67+600

Date: August 28, 2018

Photo Number: 074

Description: View of the north and west walls. Accumulation of water inside the quarry.



Photograph F1-27: Quarry 16 – km 70+400

Date: August 28, 2018

Photo Number: 078

Description: View of the south and west walls. Presence of loose rocks on steep wall.



Photograph F1-28: Quarry 16 – km 70+400

Date: August 28, 2018

Photo Number: 079

Description: View of the east wall. Presence of loose rocks on steep wall.



Photograph F1-29: Quarry 18 – km 80+200

Date: August 28, 2018

Photo Number: 082

Description: View of the south wall.



Photograph F1-30: Quarry 18 – km 80+200

Date: August 28, 2018

Photo Number: 083

Description: Looking at the north and west walls.



Photograph F1-31: Quarry 19 – km 84+300

Date: August 28, 2018

Photo Number: 086

Description: Looking at the north and west walls.



Photograph F1-32: Quarry 19 – km 84+300

Date: August 28, 2018

Photo Number: 087

Description: Looking at the north and east walls.



Photograph F1-33: Quarry 21 – km 93+400

Date: August 28, 2018

Photo Number: 091

Description: Looking at the south and east walls.



Photograph F1-34: Quarry 21 – km 93+400

Date: August 28, 2018

Photo Number: 092

Description: Looking at the north and the west walls.



Photograph F1-35: Quarry 22 – km 99+200

Date: August 28, 2018

Photo Number: 097

Description: View of the south and west walls.



Photograph F1-36: Quarry 22 – km 99+200

Date: August 28, 2018

Photo Number: 098

Description: Looking at the north and west walls.



Photograph F1-37: Quarry 23 (Airstrip Quarry)

Date: August 28, 2018

Photo Number: 101

Description: Looking at the north wall.



Photograph F1-38: Quarry 23 (Airstrip Quarry)

Date: August 28, 2018

Photo Number: 102

Description: Looking at the south wall.



Photograph F1-39: Quarry 23 (Airstrip Quarry)

Date: August 28, 2018

Photo Number: 103

Description: Looking at the north wall. Presence of loose rocks along steep wall.



Photograph F1-40: Quarry 23 (Airstrip Quarry)

Date: August 28, 2018

Photo Number: 104

Description: Looking at the north and east walls.



Photograph F1-41: Quarry 23 (Airstrip Quarry)

Date: August 28, 2018

Photo Number: 105

Description: Looking at the south and east walls.

APPENDIX F2

**Bridges Along Amaruq Road
Photographic Log**



Photograph F2-1 Eskers and Quarries 1 – km 10+500

Date: August 28, 2018

Photo Number: 373

Description: View of Quarry 10.5. Loose rock is present on the steep wall.



Photograph F2-2 Eskers and Quarries 1 – km 10+500

Date: August 28, 2018

Photo Number: 374

Description: View of Quarry 10.5. Loose rock is present on the steep wall.



Photograph F2-3 Eskers and Quarries 2 – km 25+000

Date: August 28, 2018

Photo Number: 354

Description: View of esker #2. General good condition but some steep walls and loose rocks.



Photograph F2-4 Eskers and Quarries 3 – km 30+180

Date: August 28, 2018

Photo Number: 348

Description: View of Quarry 30.5. Most walls are in unstable condition.



Photograph F2-5 Eskers and Quarries 3 – km 30+180

Date: August 28, 2018

Photo Number: 349

Description: View of Quarry 30.5. Most walls are in unstable condition.



Photograph F2-6 Eskers and Quarries 4 – km 46+000

Date: August 28, 2018

Photo Number: 339

Description: View of esker #3. North access ramp along a steep slope that seems undercut at its toe.



Photograph F2-7 Eskers and Quarries 5 – km 52+000

Date: August 28, 2018

Photo Number: 335

Description: View of the rock quarry at km 52. In good conditions with loose blocks and cobbles on the north wall.



Photograph F2-8 Eskers and Quarries 5 – km 52+000

Date: August 28, 2018

Photo Number: 336

Description: View of the rock quarry at km 52. In good conditions with loose blocks and cobbles on the north wall.



Photograph F2-9 Eskers and Quarries 6 – km 62+500

Date: August 28, 2018

Photo Number: 331

Description: View of esker #6. The 2-m high steep soil slopes are unstable.



Photograph F2-10 Eskers and Quarries 6 – km 62+500

Date: August 28, 2018

Photo Number: 332

Description: View of esker #6. The 2-m high steep soil slopes are unstable.

APPENDIX G

Quarries and Eskers

APPENDIX G1

**Baker Lake Tank Farm
Photographic Log**



Photograph G1-1 Baker Lake Tank Farm

Date: August 28, 2018

Photo Number: 003

Description: From the south side of Tank 1, looking southeast at Tanks 1, 2, 3, and 4. Presence of water ponding.



Photograph G1-2 Baker Lake Tank Farm

Date: August 28, 2018

Photo Number: 002

Description: Looking at the southwestern corner of Tank 1.



Photograph G1-3 Baker Lake Tank Farm

Date: August 28, 2018

Photo Number: 001

Description: From the north side of Tank 1, looking southeast at Tanks 1, 2, 3, and 4.



Photograph G1-4 Baker Lake Tank Farm

Date: August 28, 2018

Photo Number: 004

Description: Looking northwest toward the south side of Tank 1.



Photograph G1-5 Baker Lake Tank Farm

Date: August 28, 2018

Photo Number: 005

Description: Looking northeast toward the south side of Tanks 2 and 3.



Photograph G1-6 Baker Lake Tank Farm

Date: August 28, 2018

Photo Number: 006

Description: Looking southwest toward the south wall of the tank farm. Presence of animal burrows.



Photograph G1-7 Baker Lake Tank Farm

Date: August 28, 2018

Photo Number: 008

Description: Looking northeast. The geomembrane between the south side of tank 2 and 3 is damaged.



Photograph G1-8 Baker Lake Tank Farm

Date: August 28, 2018

Photo Number: 009

Description: From the southwestern corner of Tank 3 looking southeast. View of exposed LLDPE.



Photograph G1-9 Baker Lake Tank Farm

Date: August 28, 2018

Photo Number: 010

Description: From the southeastern corner of Tank 3, looking northwest at the south side of Tank 3, 2 and 1. View of exposed LLDPE.



Photograph G1-10 Baker Lake Tank Farm

Date: August 28, 2018

Photo Number: 011

Description: From the south portion of the site looking north at the south side of Tank 3, 4 and 5.



Photograph G1-11 Baker Lake Tank Farm

Date: August 28, 2018

Photo Number: 012

Description: From the south portion of the site looking southeast.



Photograph G1-12 Baker Lake Tank Farm

Date: August 28, 2018

Photo Number: 013

Description: From the northeastern corner of Tank 4 looking southwest toward Tank 4.



Photograph G1-13 Baker Lake Tank Farm

Date: August 28, 2018

Photo Number: 014

Description: From the northern side of Tank 4, looking northeast toward Tanks 4, 3, 2, and 1. Presence of exposed liner.



Photograph G1-14 Baker Lake Tank Farm

Date: August 28, 2018

Photo Number: 016

Description: From the northeastern corner of Tank 2 looking northwest towards the northeastern side of Tanks 1 and 2.



Photograph G1-15 Baker Lake Tank Farm

Date: August 28, 2018

Photo Number: 015

Description: From the northwestern corner of Tank 3 looking southeast towards the northeastern side of Tanks 3 and 4.



Photograph G1-16 Baker Lake Tank Farm

Date: August 28, 2018

Photo Number: 017

Description: Looking northwest at the southern and western sides of Tank 5.



Photograph G1-17 Baker Lake Tank Farm

Date: August 28, 2018

Photo Number: 018

Description: Looking north between Tanks 5 and 6. Presence of water ponding.



Photograph G1-18 Baker Lake Tank Farm

Date: August 28, 2018

Photo Number: 019

Description: Looking northeast at the southern side of Tank 6. Presence of water ponding.



Photograph G1-19 Baker Lake Tank Farm

Date: August 28, 2018

Photo Number: 021

Description: Looking southeast at the northeastern side of Tank 6. Presence of water ponding.



Photograph G1-20 Baker Lake Tank Farm

Date: August 28, 2018

Photo Number: 022

Description: Looking south between Tanks 5 and 6.



Photograph G1-21 Baker Lake Tank Farm

Date: August 28, 2018

Photo Number: 020

Description: Looking west at the northeastern side of Tank 5.



Photograph G1-22 Baker Lake Tank Farm

Date: August 28, 2018

Photo Number: 024

Description: From the northeastern corner of the Jet A fuel tanks looking south. Presence of exposed geomembrane.



Photograph G1-23 Baker Lake Tank Farm

Date: August 28, 2018

Photo Number: 023

Description: From the northeastern corner of the Jet A fuel tanks looking west. Presence of exposed geomembrane.



Photograph G1-24 Baker Lake Tank Farm

Date: August 28, 2018

Photo Number: 026

Description: From the southwestern corner of the Jet A fuel tanks looking east. Presence of exposed geomembrane and water ponding.



Photograph G1-25 Baker Lake Tank Farm

Date: August 28, 2018

Photo Number: 025

Description: From the southwestern corner of the Jet A fuel tanks looking north. Presence of exposed geomembrane and water ponding.

APPENDIX G2

Quarries and Eskers along Amaruq
Road Photographic Log



Photograph G2-1 Meadowbank Tank Farm

Date: August 29, 2018

Photo Number: 126

Description: From the western corner, looking east at the tank.



Photograph G2-2 Meadowbank Tank Farm

Date: August 29, 2018

Photo Number: 125

Description: From the western corner, looking northeast at the tank.



Photograph G2-3 Meadowbank Tank Farm

Date: August 29, 2018

Photo Number: 131

Description: From the eastern side, looking northwest.



Photograph G2-4 Meadowbank Tank Farm

Date: August 29, 2018

Photo Number: 130

Description: From the eastern side looking southwest. Presence of water ponding. A pump is installed.



Photograph G2-5 Meadowbank Tank Farm

Date: August 29, 2018

Photo Number: 128

Description: Looking northeast from the southern corner. Accumulation of water in the eastern corner.



Photograph G2-6 Meadowbank Tank Farm

Date: August 29, 2018

Photo Number: 127

Description: Looking northwest from the southern corner.



Photograph G2-7 Meadowbank Tank Farm

Date: August 29, 2018

Photo Number: 129

Description: Looking northwest from the southern corner.

APPENDIX G2

**Main Camp Tank Farm
Photographic Log**



Photograph G2-1 Meadowbank Tank Farm

Date: August 29, 2018

Photo Number: 126

Description: From the western corner, looking east at the tank.



Photograph G2-2 Meadowbank Tank Farm

Date: August 29, 2018

Photo Number: 125

Description: From the western corner, looking northeast at the tank.



Photograph G2-3 Meadowbank Tank Farm

Date: August 29, 2018

Photo Number: 131

Description: From the eastern side, looking northwest.



Photograph G2-4 Meadowbank Tank Farm

Date: August 29, 2018

Photo Number: 130

Description: From the eastern side looking southwest. Presence of water ponding. A pump is installed.



Photograph G2-5 Meadowbank Tank Farm

Date: August 29, 2018

Photo Number: 128

Description: Looking northeast from the southern corner. Accumulation of water in the eastern corner.



Photograph G2-6 Meadowbank Tank Farm

Date: August 29, 2018

Photo Number: 127

Description: Looking northwest from the southern corner.



Photograph G2-7 Meadowbank Tank Farm

Date: August 29, 2018

Photo Number: 129

Description: Looking northwest from the southern corner.

APPENDIX G3

Vault Tank Farm Photographic Log



Photograph G3-1 Vault Tank Farm

Date: August 29, 2018

Photo Number: 144

Description: From the southeast corner of the Tanks looking northwest toward the Vault Tank Farm.



Photograph G3-2 Vault Tank Farm

Date: August 29, 2018

Photo Number: 142

Description: From the northwest corner of the Tanks Looking northeast toward the Vault Tank Farm.



Photograph G3-3 Vault Tank Farm

Date: August 29, 2018

Photo Number: 145

Description: From the southwest corner of the Tanks Looking northeast toward the Vault Tank Farm.



Photograph G3-4 Vault Tank Farm

Date: August 29, 2018

Photo Number: 143

Description: From the northeast corner of the Tanks looking southwest toward the Vault Tank Farm.

APPENDIX H

Other Facilities

APPENDIX H1

Vault Road Culverts Photographic Log



Photograph H1-1 Vault Road Culverts

Date: August 29, 2018

Photo Number: 153

Description: Looking at the outlet of the three culverts located on Vault Road at 640964E/7217466N. All of them are deformed in the middle.



Photograph H1-2 Vault Road Culverts

Date: August 29, 2018

Photo Number: 154

Description: From the inlet side of the three culverts located on Vault Road at 640964E/7217466N. Looking inside the southern culvert. The culvert is slightly deformed on top in the middle.



Photograph H1-3 Vault Road Culverts

Date: August 29, 2018

Photo Number: 155

Description: From the inlet side of the three culverts located on Vault Road at 640964E/7217466N. Looking inside the central culvert. The culvert is slightly deformed on top in the middle.



Photograph H1-4 Vault Road Culverts

Date: August 29, 2018

Photo Number: 156

Description: From the inlet side of the three culverts located on Vault Road at 640964E/7217466N. Looking inside the northern culvert. The culvert is slightly deformed on top in the middle.



Photograph H1-5 Vault Road Culverts

Date: August 29, 2018

Photo Number: 157

Description: Culvert on the NP1 side at 639 214 E / 7 216 189 N on Vault Road.

APPENDIX H2

**Diversion Ditch and its Erosion and
Sediment Protection Structure
Photographic Log**



Photograph H2-1 Diversion Ditch and its Sediment and Erosion Protection Structure

Date: August 29, 2018

Photo Number: 158

Description: Looking south toward Lake NP1 at the sediment and erosion protection structure. Presence of 2 silt curtains and 3 wooden barrier.



Photograph H2-2 Diversion Ditch and its Sediment and Erosion Protection Structure

Date: August 29, 2018

Photo Number: 159

Description: Looking west toward the western diversion ditch.



Photograph H2-3 Diversion Ditch and its Sediment and Erosion Protection Structure

Date: August 29, 2018

Photo Number: 165

Description: From the eastern diversion ditch looking south toward Lake NP2.



Photograph H2-4 Diversion Ditch and its Sediment and Erosion Protection Structure

Date: August 29, 2018

Photo Number: 166

Description: From the eastern diversion ditch looking northwest.



Photograph H2-5 Diversion Ditch and its Sediment and Erosion Protection Structure

Date: August 29, 2018

Photo Number: 167

Description: From the eastern diversion ditch, looking east.



Photograph H2-6 Diversion Ditch and its Sediment and Erosion Protection Structure

Date: August 29, 2018

Photo Number: 168

Description: From the eastern diversion ditch, looking northwest.



Photograph H2-7 Diversion Ditch and its Sediment and Erosion Protection Structure

Date: August 29, 2018

Photo Number: 169

Description: From the northern diversion ditch looking southeast.



Photograph H2-8 Diversion Ditch and its Sediment and Erosion Protection Structure

Date: August 29, 2018

Photo Number: 170

Description: From the northern diversion ditch looking west.



Photograph H2-9 Diversion Ditch and its Sediment and Erosion Protection Structure

Date: August 29, 2018

Photo Number: 171

From the northern diversion ditch looking east.



Photograph H2-10 Diversion Ditch and its Sediment and Erosion Protection Structure

Date: August 29, 2018

Photo Number: 172

From the northern diversion ditch looking west.



Photograph H2-11 Diversion Ditch and its Sediment and Erosion Protection Structure

Date: August 29, 2018

Photo Number: 173

Description: From the northern diversion ditch looking east.



Photograph H2-12 Diversion Ditch and its Sediment and Erosion Protection Structure

Date: August 29, 2018

Photo Number: 174

Description: From the northern diversion ditch looking west.



Photograph H2-13 Diversion Ditch and its Sediment and Erosion Protection Structure

Date: August 29, 2018

Photo Number: 175

Description: From 637281E/7216790N, looking north. View of the western diversion ditch.



Photograph H2-14 Diversion Ditch and its Sediment and Erosion Protection Structure

Date: August 29, 2018

Photo Number: 176

Description: From 637281E/7216790N, looking south at the western diversion ditch.



Photograph H2-15 Diversion Ditch and its Sediment and Erosion Protection Structure

Date: August 29, 2018

Photo Number: 177

Description: From 637251E/7216171N, looking north at the western diversion ditch.



Photograph H2-16 Diversion Ditch and its Sediment and Erosion Protection Structure

Date: August 29, 2018

Photo Number: 178

Description: From 637251E/7216171N, looking west at the western diversion ditch and its retention basin.



Photograph H2-17 Diversion Ditch and its Sediment and Erosion Protection Structure

Date: August 29, 2018

Photo Number: 179

Description: From 637074E/7216157N, looking east at the western diversion ditch.



Photograph H2-18 Diversion Ditch and its Sediment and Erosion Protection Structure

Date: August 29, 2018

Photo Number: 180

Description: From 637074E/7216157N, looking west at the western diversion ditch.

APPENDIX H3

RSF Till Plug Photographic Log



Photograph H3-1 RSF Till Plug

Date: August 29, 2018

Photo Number: 161

Description: From the south side of NP2 Lake (north of the diversion ditch) looking west at the RSF till plug.



Photograph H3-2 RSF Till Plug

Date: August 29, 2018

Photo Number: 162

Description: From the south side of NP2 Lake (south of the diversion ditch) looking west at the RSF till plug.



Photograph H3-3 RSF Till Plug

Date: August 29, 2018

Photo Number: 163

Description: From the south side of NP2 Lake (south of the diversion ditch) looking southeast at the RSF till plug.



Photograph H3-4 RSF Till Plug

Date: August 29, 2018

Photo Number: 164

Description: From the south side of NP2 Lake (south of the diversion ditch) looking northwest at the RSF till plug.

APPENDIX H4

Diffusers Photographic Log



Photograph H4-1 Diffusers – Vault Diffuser

Date: August 29, 2018

Photo Number: 146

Description: Looking at the Diffuser at Vault. In good condition.

APPENDIX H5

Landfill Photographic Log



Photograph H5-1 Landfill

Date: August 29, 2018

Photo Number: 141

Description: From 638857E/7215767N, looking north at the landfill.



Photograph H5-2 Landfill

Date: August 29, 2018

Photo Number: 140

Description: From 638857E/7215767N, looking northwest at the landfill.

APPENDIX H6

**Contaminated Soil Storage and
Bioremedial Landfarm Facility
Photographic Log**



Photograph H6-1 Contaminated Soil Storage and Bioremedial Landfarm Facility

Date: August 29, 2018

Photo Number: 136

Description: From the northeast extremity of the South Cell, looking northwest at the Contaminated Soil Storage and Bioremedial Landfarm Facility located within the South Cell of the TSF, north of Central Dike.



Photograph H6-2 Contaminated Soil Storage and Bioremedial Landfarm Facility

Date: August 29, 2018

Photo Number: 137

Description: From the northeast extremity of the South Cell, looking northwest at the Contaminated Soil Storage and Bioremedial Landfarm Facility.



Photograph H6-3 Contaminated Soil Storage and Bioremedial Landfarm Facility

Date: August 29, 2018

Photo Number: 138

Description: From the northeast extremity of the South Cell, looking northwest at the Contaminated Soil Storage and Bioremedial Landfarm Facility.



Photograph H6-4 Contaminated Soil Storage and Bioremedial Landfarm Facility

Date: August 29, 2018

Photo Number: 139

Description: From the northeast extremity of the South Cell, looking southeast at the Contaminated Soil Storage and Bioremedial Landfarm Facility.



Photograph H6-5 Contaminated Soil Storage and Bioremedial Landfarm Facility

Date: August 29, 2018

Photo Number: 200

Description: From the northeast extremity of the South Cell, looking northwest at the Contaminated Soil Storage and Bioremedial Landfarm Facility. Sign of superficial slope failure.



Photograph H6-6 Contaminated Soil Storage and Bioremedial Landfarm Facility

Date: August 29, 2018

Photo Number: 201

Description: From Stormwater Dike, looking southeast at the Contaminated Soil Storage and Bioremedial Landfarm Facility. Rockfill was placed on overburden fill material which is probably founded on a steep natural slope.

APPENDIX H7

Stormwater Pond Photographic Log



Photograph H7-1 Stormwater Pond

Date: August 29, 2018

Photo Number: 121

Description: From the northwestern side of the pond, looking southeast at Stormwater Pond.



Photograph H7-2 Stormwater Pond


Date: August 29, 2018

Photo Number: 122

Description: From the northwestern side of the pond, looking southeast at Stormwater Pond.

APPENDIX H8

Airstrip Photographic Log



Photograph H8-1 Airstrip

Date: August 29, 2018

Photo Number: 135

Description: Looking west at the extremity of the airstrip located within Third Portage Lake.



Photograph H8-2 Airstrip

Date: August 29, 2018

Photo Number: 134

Description: From the extremity of the airstrip located within Third Portage Lake, looking southeast.



Photograph H8-3 Airstrip

Date: August 29, 2018

Photo Number: 133

Description: From the northeast side of the airstrip looking northwest.



Photograph H8-4 Airstrip

Date: August 29, 2018

Photo Number: 132

Description: From the northeast side of the airstrip looking southeast.



Photograph H8-5 Airstrip

Date: August 29, 2018

Photo Number: 124

Description: From the southeast side of the airstrip looking northwest.



Photograph H8-6 Airstrip

Date: August 29, 2018

Photo Number: 123

Description: From the southeast side of the airstrip looking east.



golder.com