



2019-03-05 WTP 350 HYDRAULIC OIL SPILL

GN reference #: 2019-087

Please find the following information as a follow up to the spill report submitted March 5th, 2019 by Agnico Eagle. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License NWB-2AM-WTP1826, Part H, Item 8c.

Spill Description

The excavator traveling to different locations in the pit, when the operator saw some oil on the undercarriage. The operator stopped immediately the equipment and he called the maintenance to fix it.

Location coordinates of the spill: Northing 65°24'9.3" Easting 96°43'14.53.5"

There were no off site impact or discharge to any receiving watercourses. Distance to the closest lake is estimated at 150 meters.

Cause of Spill

The leak was caused after a hose blew on the traction.

Remediation Actions

The operator stopped immediately the equipment and called the maintenance department to fix the problem. All contaminated soil has been removed and placed on the proper place. It will be brought at the landfarm at Meadowbank.

Corrective measures

The hydraulic system including hoses and fittings are inspected as part of the preventive maintenance program done on site. Routine visual inspection of the hydraulic system is also performed during pre-operations checks.

Closure

We trust that the above details described appropriately the spill incident that occurred at WTP on March 5th, 2019 and the follow up actions. Please contact the undersigned should you have any questions.



Martin Archambault

Environmental Senior Coordinator

martin.archambault@agnicoeagle.com

T: 819.759.3555 x6744

Agnico Eagle Mines Limited

Meadowbank Division

Baker Lake, Nunavut, Canada

X0C 0A0

agnicoeagle.com



AGNICO EAGLE

