



## 2019-06-16 WTP Quarry 2 450 Liters Hydraulic Oil

GN reference # : 2019-242

Please find the following information as a follow up to the Spill report submitted June 17<sup>th</sup>, 2019 by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-WTP1826, Part H, Item 8c.

### Spill Description

During operations the hydraulic system hose of BAC09 busted due to mechanical failure. The equipment was shut down and the contaminated material was picked up and brought to the landfarm at Meadowbank.



Spill location: N 65 24'11.3'' W 096 42'16.7''

### Cause of Spill

The spill has been caused by mechanical issue with the hose.

## Remediation Actions

When he saw the oil during his move the operator stop the shovel and called for a mechanic. All the contaminated muck was sent to the tankfarm at Meadowbank.

## Corrective measures

A routine visual inspection of all system is performed during pre-operations checks as a part of the preventive maintenance program.

## Closure

We trust that the above details described appropriately the spill incident that occurred at the Whale Tail site on June 16<sup>th</sup>, 2019 and the cleanup activities. Please contact the undersigned should you have any questions.

**Martin Archambault**  
**Environmental Senior Coordinator**  
martin.archambault@agnicoeagle.com  
T: 819.759.3555 x6744  
Agnico Eagle Mines Limited  
Meadowbank Division  
Baker Lake, Nunavut, Canada  
X0C 0A0

[agnicoeagle.com](http://agnicoeagle.com)



**AGNICO EAGLE**

