



2019-07-08 WTP 100 Liters Diesel

GN reference # : 2019-273

Please find the following information as a follow up to the Spill report submitted July 9th, 2019 by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2BB-MEA1318, Part H, Item 5c.

Spill Description

During operations at Quarry 2 of Whale Tail pit project, a rock on RBD04 drill got stuck between the track and fuel tank causing damage to the fuel tank drain plug.



Spill location: N 65° 24'25.4'' W 096° 42'22.5''

Cause of Spill

The spill has been caused rock struck between the track and fuel tank causing damage to the fuel tank drain plug.

Remediation Actions

The drill was shut down and a secondary containment bucket was put underneath the fuel tank while the drain plug was replaced. The spill occurred on a blast pattern which was collected and processed through the Mill

Corrective measures

A routine visual inspection of all system is performed during pre-operations checks as a part of the preventive maintenance program.

Closure

We trust that the above details described appropriately the spill incident that occurred at the Whale Tail site on July 9th, 2019 and the cleanup activities. Please contact the undersigned should you have any questions.



Martin Archambault
Environmental Senior Coordinator
martin.archambault@agnicoeagle.com
T: 819.759.3555 x6744
Agnico Eagle Mines Limited
Meadowbank Division
Baker Lake, Nunavut, Canada
X0C 0A0

agnicoeagle.com



AGNICO EAGLE

