



## 2019-09-10 WTP 240 Liters Coolant

GN reference # : 2019-372

Please find the following information as a follow up to the Spill report submitted September 11, 2019 by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-WTP1826, Part H, Item 8c.

### Spill Description

During operations at Whale Tail pit, the radiator hose of HTR21 let go, causing coolant to spill on the ground.



Spill location: N 65 24'27.2" W 096 43'19.9" on IOL

There were no off site impacts or discharge to any receiving watercourses. Distance to the closest lake is estimated at 500 meters.

### Cause of Spill

The spill was due to the mechanical failure of the radiator hose.

## Remediation Actions

The equipment was immediately shut down and maintenance was called to replace the broken hose. Once the hose was repaired and the equipment was moved, the contaminated material was removed and brought to the Meadowbank south cell tailings.



## Corrective measures

A routine visual inspection of all systems and hoses is performed during pre-operations checks as a part of the preventive maintenance program.

## Closure

We trust that the above details described appropriately the spill incident that occurred at the Whale Tail site on September 10, 2019 and the cleanup activities. Please contact the undersigned should you have any questions.



**Tom Thomson**  
**Environmental Coordinator**  
tom.thomson@agnicoeagle.com  
T: 819.759.3555 x4606744  
Agnico Eagle Mines Limited  
Meadowbank Division  
Baker Lake, Nunavut, Canada  
X0C 0A0

[agnicoeagle.com](http://agnicoeagle.com)



**AGNICO EAGLE**

