



2019-12-28 WTP 200 L Hydraulic Oil

GN reference #: 2019-493

Please find the following information as a follow up to the Spill report submitted December 28, 2019 by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-WTP1826, Part H, Item 8c.

Spill Description

During operations at the Waste Rock Storage Facility, the hydraulic system the haul truck failed. The equipment was immediately shutdown to prevent further spillage.



Spill location: 65° 24'40.4" 96° 43' 44.3" on IOL

There were no off site impacts or discharge to any receiving watercourses. Distance to the closest water body is estimated at 500 meters to Mammoth Lake.

Cause of Spill

The spill occurred due to a failure on the main hydraulic lines of the truck caused by cold temperatures.

Remediation Actions

The equipment was shut down and maintenance was called. Once the repairs were made, BAC13 was moved, the contaminated material was picked up and brought to the Meadowbank landfarm. Approximately 4m3 of contaminated material was collected.



Corrective measures

A routine visual inspection of all systems and hoses is performed during pre-operational checks as a part of the preventative maintenance program.

Closure

We trust that the above details described appropriately the spill incident that occurred at the Whale Tail site on December 28, 2019 and the cleanup activities. Please contact the undersigned should you have any questions.

A handwritten signature in black ink, appearing to read 'Robin Allard'.

Robin Allard | General Supervisor Environment

robin.allard@agnicoeagle.com | Direct 819.759.3555 x4606838 | Mobile 819.860.1414

Agnico Eagle Mines Limited - Meadowbank Division

