



2021-01-01 AMQ 92L Diesel fuel

GN reference #: 2021-003

Please find the following information as a follow up to the Spill report submitted January 1st, 2021 by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-WTP1830, Part H, Item 8c.

Spill Description

At surface, during refueling of a scoop, the equipment was accidentally overfilled causing 92L fuel to spill onto the ground beside underground equipment maintenance shop.



Spill location: 65 24'22.9" ; 96 40'47.9" on IOL

There were no off site impacts or discharge to any receiving watercourses. Distance to the closest water body is 1100 meters to Whale Tail south Lake.

Cause of Spill

Scoop #61sco02 was overfilled, by operator error.

Remediation Actions

The operator stopped the process and absorbent pads were immediately used to contain the spill, which covered around 6m². Approximately 1m³ of contaminated ground was collected, and disposed of, in the contaminated soil bin to be brought at the land farm in Meadowbank.



Corrective measures

Refueling procedure was revised with workers.

Closure

We trust that the above details described appropriately the spill incident that occurred at the Whale Tail site on January 1st, 2021 and the cleanup activities. Please contact the undersigned should you have any questions.



Eric Haley | Environment Coordinator

eric.haley@agnicoeagle.com | Direct 819.759.3555 x4606744 |

Agnico Eagle Mines Limited - Meadowbank Division, Suite 540 - Baker Lake, Nunavut, Canada X0C 0A0

agnicoeagle.com    