



## 2021-01-08 WTP 375L Coolant

GN reference #: 2021-008

Please find the following information as a follow up to the Spill report submitted January 9, 2021 by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-WTP1830, Part H, Item 8c.

### Spill Description

During operations, a radiator hose failure occurred on a haul truck while travelling on the Whale Tail Haul road, spilling coolant on the road.



Spill location: 65°11'40.92" 96°09'51.32" on Crown land.

There were no off site impacts or discharge to any receiving watercourses. Distance to the closest water body is 650 meters to an unnamed lake along the Whale Tail Haul road.

## Cause of Spill

Radiator Hose failure on Haul Truck 21.

## Remediation Actions

The operator stopped the truck in one of the pull outs and called maintenance. Approximately 6m<sup>3</sup> of contaminated snow and material was collected and brought to the tailings at Meadowbank.



## Corrective measures

A routine visual inspection of all systems is performed during pre-operation checks as a part of the preventative maintenance program.

## Closure

We trust that the above details described appropriately the spill incident that occurred at the Whale Tail site on January 8, 2021 and the cleanup activities. Please contact the undersigned should you have any questions.



Tom Thomson | Environment Coordinator

tom.thomson@agnicoeagle.com | Direct 819.759.3555 x4606744 |

Agnico Eagle Mines Limited - Meadowbank Division, Suite 540 - Baker Lake, Nunavut, Canada X0C 0A0

[agnicoeagle.com](http://agnicoeagle.com)

