



## 2021-05-27 WTP 150L Diesel

GN reference #: 2021-212

Please find the following information as a follow up to the Spill report submitted May 27, 2021 by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-WTP1830, Part H, Item 8c.

### Spill Description

During an Environmental inspection at the Whale Tail Pit project, a diesel fuel spill was found on the ground at the drill storage pad. An overfill during refueling on night shift is the most probable cause of this occurrence.



Spill location: 65 24'47.49" 96 41'49.71" on IOL.

There were no off site impacts or discharge to any receiving watercourses. Distance to the closest water body is 300 meters to Nemo Lake.

### Cause of Spill

Unknown but most likely due to an overfill during refilling.

## Remediation Actions

Operations supervisor requested equipment to start recovering the contaminated material immediately. The area was scraped and cleaned with a backhoe. Approximately 8m of contaminated material was collected and disposed of in the contaminated soil bin, then disposed in the Meadowbank landfarm.




## Corrective measures

A general reminder to all personal regarding spill reporting and refueling procedures was completed along with Environmental Toolbox meetings.

## Closure

We trust that the above details described appropriately the spill incident that occurred at the Whale Tail site on May 27, 2021 and the cleanup activities. Please contact the undersigned should you have any questions.



Tom Thomson | Environment Coordinator

[tom.thomson@agnicoeagle.com](mailto:tom.thomson@agnicoeagle.com) | Direct 819.759.3555 x4606744 |

Agnico Eagle Mines Limited - Meadowbank Division, Suite 540 - Baker Lake, Nunavut, Canada X0C 0A0

[agnicoeagle.com](http://agnicoeagle.com)    