




2022-03-19 WTP 250L Diesel

GN reference #: 2022-088

Please find the following information as a follow up to the Spill report submitted March 20, 2022, by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-WTP1830, Part H, Item 8c.

Spill Description

During operations at the Whale Tail pit project, the service truck ran over a rock while going up the IVR pit ramp. The rock tipped and ruptured the fuel tank causing fuel to spill onto the ground.



Spill location: 65°24'41.9"N 96°41'58.2"W on IOL.

There were no off-site impacts or discharge to any receiving watercourses. Distance to the closest water body is 340 meters to Lake C40.

Cause of Spill

Human error

Remediation Actions

Approximately 6m³ of contaminated material was excavated from the area and brought to the Meadowbank Landfarm.



Corrective measures

Operators are reminded to drive according to conditions and to advise the pit supervisor of any spill rock on the pit roads.

Closure

We trust that the above details described appropriately the spill incident that occurred at the Meadowbank Complex on March 19, 2022, and the cleanup activities. Please contact the undersigned should you have any questions.



Tom Thomson | Environment Coordinator

tom.thomson@agnicoeagle.com | Direct 819.759.3555 x4606744 |

Agnico Eagle Mines Limited - Meadowbank Division, Suite 540 - Baker Lake, Nunavut,
Canada X0C 0A0

agnicoeagle.com    

Sent from Meadowbank

