



## 2022-11-07 WTP 220L Hydraulic Oil

GN reference #: 2022-522

Please find the following information as a follow up to the Spill report submitted November 8<sup>th</sup>, 2022, by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-WTP1830, Part H, Item 8c.

### Spill Description

During operations at the Whale Tail Project, the drive shaft failed on a haul truck causing a total of 220L of hydraulic oil to spill on to the ground at the bottom of Phase 1 in the Whale Tail Pit.



Spill Location: Northing: N 65°24'12.07" W 96°42'19.26" on IOL

There were no off-site impacts or discharges. Distance to the closest water body is 775m to Mammoth Lake

### Cause of Spill

Equipment Failure

## Remediation Actions

The equipment was immediately shut off by the operator and mechanics were called to have the equipment fixed. Approximately 4 m3 of contaminated materials has been collected and will be brought to the Meadowbank Landfarm.




## Corrective measures

A routine visual inspection of all systems is performed during pre-operation checks as a part of the preventative maintenance program.

## Closure

We trust that the above details described appropriately the spill incident that occurred at the Whale Tail site on November 7, 2022, and the cleanup activities. Please contact the undersigned should you have any questions.



**Tom Thomson** | Environment Coordinator

tom.thomson@agnicoeagle.com | Direct 819.759.3555 x4606744 |

Agnico Eagle Mines Limited - Meadowbank Division, Suite 540 - Baker Lake, Nunavut, Canada X0C 0A0

[agnicoeagle.com](http://agnicoeagle.com)    

Sent from Meadowbank

