



REPORT DATE: MONTH - DAY - YEAR

NT-NU SPILL REPORT

REPORT TIME

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

XORIGINAL SPILL REPORT,

TEL: (867) 920-8130 FAX: (867) 873-6924 EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

SPILL SOURCE SPILL CAUSE	RT	PRIGINAL SPILL REPORT, REPORT NUMB		6-16-2023		06-16-2023
ADDITIONAL INFORMATION. COMMENTS. ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MAY DURING ONCORRENT WAS IMMEDIATED MAY DURING ONCORRENT WAS IMMEDIATED MAY ASSISTANCE REQUIRED. ADDITIONAL INFORMATION. COMMENTS. ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT ON Whate Tail and will be collected and brought to the Whale Tail Road. The equipment was immediately shut off by the operator and mechanic was called to have equipment fixed. The contaminated material will be collected and brought to the Whale Tail lands. K Spill Location: Northing: N 65°24'10.79" W 96°42'49.93" on IOL. There were no off-site impacts or discharges. Distance to the closest water body is 399m to Mammoth Lake Contact information: Rowan Woodall B19-759-3555 EXT.: 460-6744 DEFORM THE EXENCE ON TAKEN TO CONTACT TIME. PROPOSED AND THE EMPLOYER AND THE PROPOSED AND THE EMPLOYER AND THE PROPOSED AND THE			-			7
WHALE TAIL MINE		F APPLICABLE)	,	·	IT NUMBER (IF APPLICABLE)	LAND USE PERMIT NUM
E DEGREES 65 MINUTES 01 SECONDS 51 DEGREES 96 MINUTES 09 SECONDS 22 F RESPONSIBLE PARTY OR VESSEL NAME AGNICO EAGLE MINES LTD BAKER LAKE XOC 0AO PO.540 GANCOMPACTOR INVOLVED GONTRACTOR ADDRESS OR OFFICE LOCATION BAKER LAKE XOC 0AO PO.540 CONTRACTOR ADDRESS OR OFFICE LOCATION GONTRACTOR ADDRESS OR OFFICE LOCATION CONTRACTOR ADDRESS OR OFFICE LOCATION CONTRACTO	ION OR OCEAN	☐ ADJACENT JURISDIC		CTION FROM NAMED LC		`
RESPONSIBLE PARTY OR VESSEL NAME AGNICO EAGLE MINES LTD BAKER LAKE XOC 0A0 PO.540 GANY CONTRACTOR INVOLVED CONTRACTOR ADDRESS OR OFFICE LOCATION PAPEDUCT SPILLED COUNTRY IN LITRES, KILOGRAMS OR CUBIC METRES U.N. NUMBER HYDRAULIC OIL SECOND PRODUCT SPILLED (IF APPLICABLE) CULANTITY IN LITRES, KILOGRAMS OR CUBIC METRES U.N. NUMBER AREA OF CONTAMINATION IN SOUARE MET EQUIPMENT FAILURE 15m2 FACTORS AFFECTING SPILL OR RECOVERY DESCRIBE ANY ASSISTANCE REQUIRED ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MAY During operations at the Whale Tail Mine, the excavator was in the motion of walking to a pad will hydraulic hose broke resulting in 250L of hydraulic oil to spill onto the ground of the Whale Tail Road. The equipment was immediately shut off by the operator and mechanic was called to have equipment fixed. The contaminated material will be collected and brought to the Whale Tail lands K Spill Location: Northing: N 65°24'10.79" W 96°42'49.93" on IOL There were no off-site impacts or discharges. Distance to the closest water body is 399m to Mammoth Lake Contact information: Rowan Woodall 819-759-3555 EXT.: 460-6744 L REPORTED TO SPILL LINE BY POSITION EMPLOYER ROWAN WOODALL REPORTED TO SPILL LINE BY POSITION EMPLOYER ANY ALTERNATE CONTACT REPORT LINE USE ONLY N PROBING EMPLOYER AGENCY CONTACT NAME CONTACT ME PROPRIES OR FRENCY TIME REPORT LINE USE ONLY REMARKS RESPONSIBLE ART ACCORDANO REPORT LINE USE ONLY REMARKS RESPONSIBLE ART ACCORDANO REMARKS REPORT LINE USE ONLY REMARKS	SECONDS 21	MINUTES 09	00	SECONDS 51	MINUTES 01	
HYDRAULIC OIL SECOND PRODUCT SPILLED HYDRAULIC OIL SECOND PRODUCT SPILLED (IF APPLICABLE) QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES U.N. NUMBER AREA OF CONTAMINATION IN SQUARE MET EXCAVATOR EQUIPMENT FAILURE JESCAVATOR ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MAY During operations at the Whale Tail Mine, the excavator was in the motion of walking to a pad whydraulic hose broke resulting in 250L of hydraulic oil to spill onto the ground of the Whale Tail Road. The equipment was immediately shut off by the operator and mechanic was called to have equipment fixed. The contaminated material will be collected and brought to the Whale Tail lands K Spill Location: Northing: N 65°24'10.79" W 96°42'49.93"on IOL There were no off-site impacts or discharges. Distance to the closest water body is 399m to Mammoth Lake Contact information: Rowan Woodall 819-759-3555 EXT.: 460-6744 L REPORTED TO SPILL LINE BY ROWAN WOODALL STATEMATE CONTACT ROBIN ANY ALTERNATE CONTACT ROBIN ANY AL		N			ARTY OR VESSEL NAME	_ RESPONSIBLE PARTY
HYDRAULIC OIL SECOND PRODUCT SPILLED (IF APPLICABLE) OUNNITTY IN LITRES, KILOGRAMS OR CUBIC METRES UN. NUMBER AREA OF CONTAMINATION IN SQUARE MET SPILL SOURCE EXCAVATOR FACTORS AFFECTING SPILL OR RECOVERY DESCRIBE ANY ASSISTANCE REQUIRED ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MAY During operations at the Whale Tail Mine, the excavator was in the motion of walking to a pad will hydraulic hose broke resulting in 250L of hydraulic oil to spill onto the ground of the Whale Tail Road. The equipment was immediately shut off by the operator and mechanic was called to have equipment fixed. The contaminated material will be collected and brought to the Whale Tail lands K Spill Location: Northing: N 65°24'10.79" W 96°42'49.93" on IOL There were no off-site impacts or discharges. Distance to the closest water body is 399m to Mammoth Lake Contact information: Rowan Woodall 819-759-3555 EXT.: 460-6744 L REPORTED TO SPILL LINE BY ROWAN WOODALL BP. COORDINATE CONTACT ROBIN Allard POSITION REPORTED TO SPILL LINE BY ROSITION REPORT LINE USE ONLY REPORT LINE US			ESS OR OFFICE LOCATION	CONTRACTOR A	DR INVOLVED	
SPILL SOURCE EXCAVATOR EQUIPMENT FAILURE J FACTORS AFFECTING SPILL OR RECOVERY DESCRIBE ANY ASSISTANCE REQUIRED ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MY During operations at the Whale Tail Mine, the excavator was in the motion of walking to a pad whydraulic hose broke resulting in 250L of hydraulic oil to spill onto the ground of the Whale Tail Road. The equipment was immediately shut off by the operator and mechanic was called to have equipment fixed. The contaminated material will be collected and brought to the Whale Tail lands K Spill Location: Northing: N 65°24'10.79" W 96°42'49.93"on IOL There were no off-site impacts or discharges. Distance to the closest water body is 399m to Mammoth Lake Contact information: Rowan Woodall 819-759-3555 EXT.: 460-6744 L REPORTED TO SPILL LINE BY ROWAN Woodall Env. Coordinator Agnico Eagle Mines ANY ALTERNATE CONTACT Robin Allard POSITION ENPLOYER ANY ALTERNATE CONTACT Robin Allard POSITION ENPLOYER ANY ALTERNATE CONTACT ROBIN AND ANY ALTERNATE CONTACT ROBIN AND ANY ALTERNATE CONTACT ROBIN ANY ALTERNATE CONTACT ROBIN AND ANY ALTERNATE CONTACT ROBIN ANY ALTERNATE CONTACT ROBIN AND ANY ALTERNATE CONTACT ROBIN AND ANY ALTERNATE CONTACT ROBIN AND ANY ALTERNATE CONTACT ROBIN ANY ALTERNATE CONTACT ROBIN AND ANY ALTERNATE CONTACT ROBIN ANY ALTERNATE CON		U.N. NUMBER	KILOGRAMS OR CUBIC METRES			HYDRAULIC (
EXCAVATOR EQUIPMENT FAILURE J FACTORS AFFECTING SPILL OR RECOVERY DESCRIBE ANY ASSISTANCE REQUIRED ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MAY During operations at the Whale Tail Mine, the excavator was in the motion of walking to a pad why hydraulic hose broke resulting in 250L of hydraulic oil to spill onto the ground of the Whale Tail Road. The equipment was immediately shut off by the operator and mechanic was called to have equipment fixed. The contaminated material will be collected and brought to the Whale Tail lands K Spill Location: Northing: N 65°24'10.79" W 96°42'49.93"on IOL There were no off-site impacts or discharges. Distance to the closest water body is 399m to Mammoth Lake Contact information: Rowan Woodall 819-759-3555 EXT.: 460-6744 L REPORTED TO SPILL LINE BY ROWAN Woodall Env. Coordinator Report LINE USE ONIX REPORT LINE USE ONLY RECEIVED AT SPILL LINE BY POSITION RECEIVED AT SPILL LINE BY POSITION RECEIVED AT SPILL LINE BY POSITION REPORT LINE USE ONLY REPORT		U.N. NUMBER	KILOGRAMS OR CUBIC METRES	QUANTITY IN LIT	CT SPILLED (IF APPLICABLE)	SECOND PRODUCT SP
ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MAY During operations at the Whale Tail Mine, the excavator was in the motion of walking to a pad whydraulic hose broke resulting in 250L of hydraulic oil to spill onto the ground of the Whale Tail Road. The equipment was immediately shut off by the operator and mechanic was called to have equipment fixed. The contaminated material will be collected and brought to the Whale Tail lands. K Spill Location: Northing: N 65°24'10.79" W 96°42'49.93"on IOL. There were no off-site impacts or discharges. Distance to the closest water body is 399m to Mammoth Lake Contact information: Rowan Woodall 819-759-3555 EXT.: 460-6744 L REPORTED TO SPILL LINE BY ROWAN Woodall Env. Coordinator Agnico Eagle Mines Meadowbank 819-759. M RY ALTERNATE CONTACT Env. Gen. Supervisor Agnico Eagle Mines REPORT LINE USE ONLY RECEIVED AT SPILL LINE BY POSITION EMPLOYER AGENCY BENDANCE OF REPORT LINE STATION OPERATOR BENDANCE MINOR MAJOR UNKNOWN FILE STATUS OPEN 1 LEAD AGENCY CONTACT NAME CONTACT TIME REMARKS	AREA OF CONTAMINATION IN SQUARE METRES 15m2					
During operations at the Whale Tail Mine, the excavator was in the motion of walking to a pad whydraulic hose broke resulting in 250L of hydraulic oil to spill onto the ground of the Whale Tail Road. The equipment was immediately shut off by the operator and mechanic was called to have equipment fixed. The contaminated material will be collected and brought to the Whale Tail lands. K Spill Location: Northing: N 65°24'10.79" W 96°42'49.93"on IOL There were no off-site impacts or discharges. Distance to the closest water body is 399m to Mammoth Lake Contact information: Rowan Woodall 819-759-3555 EXT.: 460-6744 L REPORTED TO SPILL LINE BY ROWAN WOODALL Env. Coordinator Agnico Eagle Mines Meadowbank 819-759-3555 EXT.: 460-6744 M ANY ALTERNATE CONTACT ROBIN CONTACT ROBIN Allard POSITION ENV. Gen. Supervisor Agnico Eagle Mines Meadowbank 819-860. REPORT LINE USE ONLY N RECEIVED AT SPILL LINE BY POSITION STATION OPERATOR POSITION REPORT LINE PRICE PROPERTY OPEN TO SIGNIFICANCE MINOR MAJOR UNKNOWN FILE STATUS OPEN TO SIGNIFICANCE MINOR MAJOR M	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT		DESCRIBE ANY ASSISTANCE REQUIRED		FACTORS AFFECTING SPILL OR RECOVERY	
Rowan Woodall ANY ALTERNATE CONTACT Robin Allard POSITION Env. Gen. Supervisor REPORT LINE USE ONLY RECEIVED AT SPILL LINE BY STATION OPERATOR REPORT LINE USE ONLY STATION OPERATOR REPORT LINE USE ONLY STATION OPERATOR REPORT LINE USE ONLY STATION OPERATOR REPORT LINE STATION OPERATOR REPORT L		nechanic was ca	v the operator and	diately shut of		
RECEIVED AT SPILL LINE BY POSITION STATION OPERATOR POSITION STATION OPERATOR STATION OPERATOR STATION OPERATOR STATION OPERATOR SIGNIFICANCE MINOR MAJOR UNKNOWN FILE STATUS OPEN 12 AGENCY CONTACT NAME CONTACT TIME REMARKS			be collected and broad broad 49.93" on IOL stance to the closes	ted material w 4'10.79" W 96° or discharges.	t fixed. The contamina tion: Northing: N 65°2 e no off-site impacts o Lake	equipment fix Spill Location There were no Mammoth Lal
N RECEIVED AT SPILL LINE BY POSITION STATION OPERATOR EMPLOYER LOCATION CALLED YELLOWKNIFE, NT (867) 920-8130 LEAD AGENCY EC CCG GNWT GN ILA INAC NEB TC SIGNIFICANCE MINOR MAJOR UNKNOWN FILE STATUS OPEN DESCRIPTION OF THE STATUS OPEN	9m to	t water body is 39	be collected and broad b	ted material w 4'10.79" W 96° or discharges. odall 819-759-	t fixed. The contamination: Northing: N 65°24 te no off-site impacts of Lake Information: Rowan Wo	equipment fix Spill Location There were no Mammoth Lal Contact inform REPORTED TO SPILL LI
STATION OPERATOR STATION OPERATOR SIGNIFICANCE MINOR MAJOR UNKNOWN FILE STATUS OPEN DESCRIPTION AGENCY CONTACT NAME CONTACT TIME REMARKS	9m to TELEPHONE	t water body is 39 DOCATION CALLING FROM Meadowbank LTERNATE CONTACT	be collected and broad 49.93" on IOL stance to the closes 55 EXT.: 460-6744 OYER nico Eagle Mines	ted material w 4'10.79" W 96° or discharges. odall 819-759-	t fixed. The contamination: Northing: N 65°26 te no off-site impacts of Lake Information: Rowan Work Incomplete By Position Env. Coord Contact Position	equipment fix Spill Location There were no Mammoth Lal Contact inform REPORTED TO SPILL LI ROWAN WOOD
AGENCY CONTACT NAME CONTACT TIME REMARKS	9m to TELEPHONE 819-759-3555 ALTERNATE TELEPHONE	t water body is 39 DOCATION CALLING FROM Meadowbank LTERNATE CONTACT	A9.93"on IOL stance to the closes EXT.: 460-6744 OYER nico Eagle Mines	ted material w 4'10.79" W 96° or discharges. odall 819-759- dinator	t fixed. The contamination: Northing: N 65°26 te no off-site impacts of Lake Information: Rowan Work Incomplete By Position Env. Coord Contact Position	equipment fix Spill Location There were no Mammoth Lal Contact inform REPORTED TO SPILL LI ROWAN WOOD
	9m to TELEPHONE 819-759-3555 ALTERNATE TELEPHONE	Decation calling from Meadowbank LITERNATE CONTACT Meadowbank Decation called	De collected and broad 49.93" on IOL stance to the closes 55 EXT.: 460-6744 OYER nico Eagle Mines COYER nico Eagle Mines EONLY OYER LUCYER LU	dinator Supervisor	t fixed. The contaminal tion: Northing: N 65°24 te no off-site impacts of Lake Information: Rowan Work PILL LINE BY POSITION Env. Coord Contact Position Env. Gen.	equipment fix Spill Location There were no Mammoth Lal Contact inform REPORTED TO SPILL LI ROWAN WOOD ANY ALTERNATE CONT. Robin Allard
LEAD AGENCY	9m to TELEPHONE 819-759-3555 ALTERNATE TELEPHONE 819-860-1414 REPORT LINE NUMBER	DOCATION CALLING FROM Meadowbank LITERNATE CONTACT Meadowbank DOCATION CALLED ELLOWKNIFE, NT	De collected and broad 49.93" on IOL stance to the closes 55 EXT.: 460-6744 DOYER nico Eagle Mines COYER NICOYER NICOY	dinator Supervisor REPORT LINE	t fixed. The contaminal tion: Northing: N 65°24 te no off-site impacts of Lake Information: Rowan Work Contact Position Env. Coord Contact Position Env. Gen.	REPORTED TO SPILL LING ANY ALTERNATE CONT. RECEIVED AT SPILL LING RE
	9m to TELEPHONE 819-759-3555 ALTERNATE TELEPHONE 819-860-1414 REPORT LINE NUMBER (867) 920-8130	DOCATION CALLING FROM Meadowbank LTERNATE CONTACT Meadowbank DOCATION CALLED ELLOWKNIFE, NT DR UNKNOWN FILE	De collected and broad 49.93" on IOL stance to the closes 55 EXT.: 460-6744 OYER nico Eagle Mines OYER nico Eagle Mines E ONLY OYER NICO Eagle Mines E ONLY	dinator Supervisor REPORT LINE	t fixed. The contamination: Northing: N 65°26 e no off-site impacts of Lake Information: Rowan Work Env. Coord Contact Position Env. Gen. Station operators and Station operators are compact of the contact Position Env. Gen. Station operators of the contact Position Env. Gen. Station operators of the contact Position Env. Gen. Station operators of the contact Position Station operators of the contact Position Env. Gen. Station operators of the contact Position Station operators of the contamination in the contact Position Env. Coord In the contact Position In the contact	equipment fix Spill Location There were no Mammoth Lal Contact inform REPORTED TO SPILL LIF ROWAN WOOD ANY ALTERNATE CONT. Robin Allard RECEIVED AT SPILL LIF EAD AGENCY EC CC
FIRST SUPPORT AGENCY	9m to TELEPHONE 819-759-3555 ALTERNATE TELEPHONE 819-860-1414 REPORT LINE NUMBER (867) 920-8130	DOCATION CALLING FROM Meadowbank LTERNATE CONTACT Meadowbank DOCATION CALLED ELLOWKNIFE, NT DR UNKNOWN FILE	De collected and broad 49.93" on IOL stance to the closes 55 EXT.: 460-6744 OYER nico Eagle Mines OYER nico Eagle Mines E ONLY OYER NICO Eagle Mines E ONLY	dinator Supervisor REPORT LINE	t fixed. The contamination: Northing: N 65°26 e no off-site impacts of Lake Information: Rowan Work Env. Coord Contact Position Env. Gen. Station operators and Station operators are compact of the contact Position Env. Gen. Station operators of the contact Position Env. Gen. Station operators of the contact Position Env. Gen. Station operators of the contact Position Station operators of the contact Position Env. Gen. Station operators of the contact Position Station operators of the contamination in the contact Position Env. Coord In the contact Position In the contact	equipment fix Spill Location There were no Mammoth Lal Contact inform REPORTED TO SPILL LIF ROWAN WOOD ANY ALTERNATE CONT. Robin Allard RECEIVED AT SPILL LIF EAD AGENCY EC CC
SECOND SUPPORT AGENCY	9m to TELEPHONE 819-759-3555 ALTERNATE TELEPHONE 819-860-1414 REPORT LINE NUMBER (867) 920-8130	DOCATION CALLING FROM Meadowbank LTERNATE CONTACT Meadowbank DOCATION CALLED ELLOWKNIFE, NT DR UNKNOWN FILE	De collected and broad 49.93" on IOL stance to the closes 55 EXT.: 460-6744 OYER nico Eagle Mines OYER nico Eagle Mines E ONLY OYER NICO Eagle Mines E ONLY	dinator Supervisor REPORT LINE	t fixed. The contamination: Northing: N 65°26 e no off-site impacts of Lake Information: Rowan Work Env. Coord Env. Coord Env. Gen. Station operator Contact Position Env. Gen. Station operator Contact Incomplete Contact In	equipment fix Spill Location There were no Mammoth Lal Contact inform REPORTED TO SPILL LI ROWAN WOOD ANY ALTERNATE CONT. Robin Allard RECEIVED AT SPILL LIF EAD AGENCY GENCY EAD AGENCY
THIRD SUPPORT AGENCY	9m to TELEPHONE 819-759-3555 ALTERNATE TELEPHONE 819-860-1414 REPORT LINE NUMBER (867) 920-8130	DOCATION CALLING FROM Meadowbank LTERNATE CONTACT Meadowbank DOCATION CALLED ELLOWKNIFE, NT DR UNKNOWN FILE	De collected and broad 49.93" on IOL stance to the closes 55 EXT.: 460-6744 OYER nico Eagle Mines OYER nico Eagle Mines E ONLY OYER NICO Eagle Mines E ONLY	dinator Supervisor REPORT LINE	t fixed. The contamination: Northing: N 65°26 e no off-site impacts of Lake Information: Rowan Work PILL LINE BY POSITION Env. Coord and POSITION Env. Gen.	equipment fix Spill Location There were no Mammoth Lal Contact inform REPORTED TO SPILL LI ROWAN WOOD ANY ALTERNATE CONT. Robin Allard RECEIVED AT SPILL LIF EAD AGENCY EC CC GENCY EAD AGENCY IRST SUPPORT AGENCY