



AGNICO EAGLE

2025-01-11 WTM 100L Coolant

GN reference #: 2025-037

Please find the following information as a follow up to the Spill report submitted January 12th, 2025, by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector as requested as due diligence and without prejudice by Agnico Eagle Mines Ltd. and in accordance with the conditions under the Nunavut Water Board License 2AM-WTP1830, Part H, Item 8c.

Spill Description

During operations at Whale Tail, a haul truck was exiting the pit on the phase 2 ramp when the coolant hose failed causing coolant to spill on the ground.

Spill location: 65°24'28.77"N 96°42'14.55"W on IOL.

The spill was within the active mining area of Whale Tail Pit. There were no off-site impacts or discharges. Distance to the closest water body is 900m to Nemo Lake.

Cause of Spill

Mechanical Failure.

Remediation Actions

The equipment was shut down to stop the leak until the hose was repaired. Approximately 8.0 m³ of contaminated snow and material was collected and brought to the Meadowbank Tailings Storage Facility.



Corrective measures






Routine visual inspections during pre-op checks and a more thorough preventive maintenance done by the maintenance department will continue as part of AEM's preventative maintenance program.

Closure

We trust that the above details described appropriately the spill incident that occurred at the Whale Tail site on January 11th, 2025, and the cleanup activities. Please contact the undersigned should you have any questions.

Regards,



Tom Thomson | Environmental Coordinator
tom.thomson@agnicoeagle.com | Direct 819.759.3555 | 4606744
Agnico Eagle Mines Limited - Meadowbank Division, Suite 540 - Baker Lake, Nunavut, Canada X0C 0A0
agnicoeagle.com     
Sent from Meadowbank