

#### 2025-01-28 WTM 10L Sewage

GN reference #: 2025-088

Please find the following information as a follow up to the Spill report submitted January 29<sup>th</sup>, 2025, by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-WTP1830, Part H, Item 8c.

# **Spill Description**

During operations at Whale Tail Mine, a lift station pump became plugged with foreign material (baby wipes). As a result, the lift station containment overflowed into the building and subsequently 10L of sewage left the building and spilled onto the ground.



Spill Location: 65°01'.51"N 96°09'21"W (on IOL)

The spill remained within the mine footprint. There were no off-site impacts or discharges. Distance to the closest water body is ≈360m to lake A-56.

# Cause of Spill

Human Error – Non-Flushable wipes were improperly disposed of into the septic system.

## **Remediation Actions**

The foreign objects were removed from the septic system. Lids for lift stations to be secured down after inspections.



# **Corrective measures**

General site reminder for camp residents of proper hygiene product disposal.

# <u>Closure</u>

We trust that the above details described appropriately the spill incident that occurred at the Whale Tail site on January 28<sup>th</sup>, 2025, and the cleanup activities. Please contact the undersigned should you have any questions.

