



2025-02-16 WTM 200L Hydraulic Oil

GN reference #: 2025-100

Please find the following information as a follow up to the Spill report submitted February 17th, 2025, by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-WTP1830, Part H, Item 8c.

Spill Description

During operations at Whale Tail Mine, the Hyster was traveling through Pad C when the hydraulic hose failed causing a spill of approximately 200L onto the ground.



Spill Location: 65°24'13.32"N 96°41'0.21"W (on IOL)

The spill remained within the mine footprint. There were no off-site impacts or discharges. Distance to the closest water body is 600m to Whale Tail South Lake.

Cause of Spill

Mechanical Failure.

Remediation Actions

The equipment was stopped and shut down. Absorbents were placed on the ground and a grader was called to scrape the road. Approximately 5m³ of contaminated snow and material was collected and brought to the Whale Tail Landfarm.



Corrective measures

Routine visual inspections during pre-op checks and a thorough preventative maintenance done by maintenance department will continue as part of AEM's preventative maintenance program.

Closure

We trust that the above details described appropriately the spill incident that occurred at the Whale Tail site on February 16th, 2025, and the cleanup activities. Please contact the undersigned should you have any questions.



Tom Thomson | Environmental Coordinator

tom.thomson@agnicoeagle.com | Direct 819.759.3555 | 4606744

Agnico Eagle Mines Limited - Meadowbank Division, Suite 540 - Baker Lake, Nunavut, Canada X0C 0A0

agnicoeagle.com