



2025-04-25 WTM 150L Windshield washer fluid

GN reference #:186

Please find the following information as a follow up to the Spill report submitted April 23rd, 2025, by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-WTP1830, Part H, Item 8c.

Spill Description

During operations at Whale Tail Mine, a hose connected to a methane-based windshield washer tote failed causing a spill of approximately 150L onto the ground.



Spill Location: 65°24'10.15"N 96°39'59.71"W (on IOL)

The spill remained within the mine operations footprint. There were no off-site impacts or discharges. Distance to the closest water body is approximately 375m to Lake A56.

Cause of Spill

Equipment Failure.

Remediation Actions

The main valve on the tote was closed. An auxiliary equipment was called to collect the contaminated material. Approximately 2m3 of contaminated snow and material was brought to the designated roll off bin. The bin was brought to the Meadowbank Tailing Storage Facility for disposal.



Corrective measures

Routine visual inspections of the equipment and a thorough preventative maintenance done by the energy and infrastructure department will continue as part of AEM's preventative maintenance program.

Closure

We trust that the above details described appropriately the spill incident that occurred at the Whale Tail site on April 23rd, 2025, and the cleanup activities. Please contact the undersigned should you have any questions.



Tom Thomson | Environmental Coordinator

tom.thomson@agnicoeagle.com | Direct 819.759.3555 | 4606744

Agnico Eagle Mines Limited - Meadowbank Division, Suite 540 - Baker Lake, Nunavut, Canada X0C 0A0

agnicoeagle.com     