



2025-06-19 WTM 105L Coolant

GN reference #: 2025-265

Please find the following information as a follow up to the Spill report submitted June 19th, 2025, by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-WTP1830, Part H, Item 8c.

Spill Description

While working on top of the IVR Waste Rock Storage Facility, the coolant tank of Dozer 7 leaked due to mechanical failure. This caused 105L of coolant to leak onto the ground. The spill occurred in an active material deposition area.



Spill Location: 65°24'50.1"N 96°40'04.1"W (on IOL)

The spill remained within the mine operations footprint. There were no offsite impacts or discharges. Distance to the closest water body is 1000m to Lake A113.

Cause of Spill

Mechanical Failure.

Remediation Actions

A grader was deployed to scrape the area where the spill occurred to remove as much of the spilled coolant as possible. All contaminated materials were removed and disposed of to the designated roll off bin. The bin was brought to the Meadowbank Tailings Storage Facility.



Corrective measures

Routine visual inspections during pre-op checks and a more thorough preventive maintenance done by the maintenance department will continue as part of AEM's preventative maintenance program.

Closure

We trust that the above details described appropriately the spill incident that occurred at the Whale Tail site on June 19th, 2025, and the cleanup activities. Please contact the undersigned should you have any questions.



Rowan Woodall | Environmental Supervisor

rowan.woodall@agnicoeagle.com | Direct 819.759.3555 | 4606744

Agnico Eagle Mines Limited - Meadowbank Division, Suite 540 - Baker Lake, Nunavut, Canada X0C 0A0

agnicoeagle.com     