




2025-07-30 WTM 200L Hydraulic Oil

GN reference #: 2025-308

Please find the following information as a follow up to the Spill report submitted July 30th, 2025, by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-WTP1830, Part H, Item 8c.

Spill Description

During operations at Whale Tail Mine a haul truck was parked at the IVR parking when the hydraulic line failed. As a result, ~200L of hydraulic oil to leak onto the ground. The haul truck was shut down to stop the leaking. The spill did not occur in an active excavation or deposition area.



Spill Location: 65°24'41.78"N 96°40'55.52"W (on IOL)

The spill remained within the mine operations footprint. There were no off-site impacts or discharges. Distance to the closest water body is 700m to Lake A113.

Cause of Spill

Mechanical Failure.

Remediation Actions

The haul truck was shut down to stop the leaking. A heavy equipment was deployed to scrape the area where the spill occurred. All contaminated material was removed and brought to the Whale Tail Landfarm.



Corrective measures

Routine visual inspections during pre-op checks and a more thorough preventive maintenance done by the maintenance department will continue as part of AEM's preventative maintenance program.

Closure

We trust that the above details described appropriately the spill incident that occurred at the Whale Tail site on July 30th, 2025, and the cleanup activities. Please contact the undersigned should you have any questions.



Samuel Tapp | Environment Coordinator

samuel.tapp@agnicoeagle.com | Direct 819.759.3555 x4606744 |

Agnico Eagle Mines Limited - Meadowbank Division, Suite 540 - Baker Lake, Nunavut, Canada X0C 0A0

agnicoeagle.com     

Sent from Amaruk