



2025-11-14 WTM 350L Hydraulic Oil IVR Pit

GN reference #: 2025-438

Please find the following information as a follow up to the Spill report submitted November 14th, 2025, by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-WTP1830, Part H, Item 8c.

Spill Description

During operations at Whale Tail Mine, an excavator's hydraulic hose failed inside of the pump compartment room resulting in a spill of 350L onto the floor of the IVR Pit Extension within an area of active excavation.



Spill Location: 65°24'83.70"N 96°41'50.49"W on IOL

The spill remained within the mine operations footprint. There were no off-site impacts or discharges. Distance to the closest water body is ~500m to Nemo Lake.

Cause of Spill

Mechanical Failure – wear and tear

Remediation Actions

The equipment was stopped and shut down. Maintenance and Auxiliary equipment were called to repair and collect the contaminated material. Approximately 9m³ of contaminated snow and material was collected and brought to the Whale Tail Landfarm.



Corrective measures

An extensive mechanical assessment of the unit was conducted. Routine visual inspections during pre-op checks and a thorough preventative maintenance done by maintenance department will continue as part of AEM's preventative maintenance program.

Closure

We trust that the above details described appropriately the spill incident that occurred at the Whale Tail site on November 14th, 2025, and the cleanup activities. Please contact the undersigned should you have any questions.



Rowan Woodall | Environmental Supervisor

rowan.woodall@agnicoeagle.com | Direct 819.759.3555 | 4606744

Agnico Eagle Mines Limited - Meadowbank Division, Suite 540 - Baker Lake, Nunavut
0A0

agnicoeagle.com

