



## 2025-11-29 WTM 200L Hydraulic Oil

GN reference #: 2025-447

Please find the following information as a follow up to the Spill report submitted November 29<sup>th</sup>, 2025, by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-WTP1830, Part H, Item 8c.

### Spill Description

During operations at Whale Tail Mine a hydraulic hose failed while a bolter was parked at the Underground Maintenance Shop Parking.



Spill Location: 65°24'21.39"N 96°40'45.38"W (on IOL)

The spill remained within the mine operations footprint. There were no off-site impacts or discharges. Distance to the closest water body is ~925m to Whale Tail South Lake.

### Cause of Spill

Mechanical Failure – wear and tear

## Remediation Actions

The unit was stopped and absorbent material was placed to collect the spill. The contaminated absorbents were collected, segregated and disposed Hazmat area. ~1m3 of contaminated material was collected and brought to the Whale Tail Landfarm.



## Corrective measures

An extensive mechanical assessment of the unit was conducted. Routine visual inspections during pre-op checks and a thorough preventative maintenance done by maintenance department will continue as part of AEM's preventative maintenance program.

## Closure

We trust that the above details described appropriately the spill incident that occurred at the Whale Tail site on November 29<sup>th</sup>, 2025, and the cleanup activities. Please contact the undersigned should you have any questions.



**Rowan Woodall** | Environmental Supervisor

[rowan.woodall@agnicoeagle.com](mailto:rowan.woodall@agnicoeagle.com) | Direct 819.759.3555 | 4606744

Agnico Eagle Mines Limited - Meadowbank Division, Suite 540 - Baker Lake, Nunavut  
0A0

[agnicoeagle.com](http://agnicoeagle.com)     