



The meteorological station – looking west from the Boneyard



The north end of the Boneyard – looking west



The north end of the Landfarm – looking south



The southeast corner of the Landfarm – looking north



A general overview of the Boneyard – looking north

| | | | | |
|---|---|------------------------------|--------------|------------|
|  |  | 2014 Geotechnical Inspection | | |
| | | Landfarm and Bone Yard | | |
| Job No: 1CT022.000 Filename: Boston Geotech_Figures2014.pptx | HOPE BAY PROJECT | Date: Dec 2014 | Approved: LW | Figure: 19 |



Condition of the rock face on the left side of the Portal entrance



Condition of the reinforcement over the Portal entrance



Condition of the rock face on the right side of the Portal entrance



The Incinerator – looking south from the Portal Entrance



The Portal Entrance – looking southeast

| | | | | |
|--|--|------------------------------------|-----------------|----------------------|
|  Job No: 1CT022.000 Filename: Boston Geotech_Figures2014.pptx |  HOPE BAY PROJECT | 2014 Geotechnical Inspection | | |
| | | Portal and Incinerator Area | | |
| | | Date: Dec 2014 | Approved: LW | Figure: 20 |



STP Discharge Location – looking north



New STP – looking west along the Road to Dock



Boston Camp – looking south from the Road to Dock by the New STP



Historic Fuel Spill Area by the Helipad – looking south towards the Machine Shop



Old STP – looking east towards Boston Camp



Fresh water intake pipe line – looking south