

WATER USE INSPECTION REPORT

| | |
|------------------------|---|
| Date: August 8, 2009 | Licensee Rep. (Name/Title): Sylvain Doire, Stephan Robert, Denis Vaillancourt |
| Licensee: Agnico Eagle | Licence No: 2BE-MEA0813 |

WATER SUPPLY

| | | | |
|--|-----------------------------|---|-----------------------------|
| Source(s): Third Portage Lake | | Quantity used: Unknown – Unknown | |
| Owner:/Operator: Agnico-Eagle Ltd. | | Usage records (drill) submitted by E-mail | |
| Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected | | | |
| Intake Facilities: NI | Storage Structure: A | Treatment Sys: NA | Chemical Storage: NA |
| Flow Meas. Device: NA | Conveyance Lines: NA | Pumping Stations: NA | Screen : NA |

Comments: Water is pumped from the lake and then treated at the Exploration Camp. Water usage records were reviewed for Camp and drilling activities. Meters are installed as required.

WASTE DISPOSAL

Sewage: Sewage Treatment System (Prim./Sec/Ter.): Treatment at mine site

| | | | |
|-----------------------------------|--|------------|--|
| Natural Water Body: Teardrop lake | Continuous Discharge (land or water): Continuous | | |
| Seasonal Discharge: NA | Wetlands Treatment: NA | Trench: NA | |

Comments: Sewage wastes are being hauled to mine site for treatment and discharge. Camp sump is insufficient to handle the volume of water generated. The licensee is required to construct a sump of sufficient size and depth to achieve compliance with the issued Water License.

Solid Waste: Landfill

| | | |
|--|-----------------------------|----------------------------|
| Landfill: Constructed at mine site | Burn & Landfill: NA | Other: Incinerator on site |
| Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected | | |
| Discharge Quality: | Decant Structure: | Erosion: A |
| Discharge Meas. Device: NA | Dyke Inspection: NA | Seepages: A |
| Dams, Dykes: NI | Freeboard: A | Spills: NI |
| Construction: NI | O&M Plan: NI | A&R Plan: NI |
| Periods of Discharge: NA. | Effluent Discharge Rate: NA | |

Comments: Solid waste is hauled to the mine site for incineration. Metals waste has been stored in Quarry 22. An Inspection of Quarry 6, Quarry 22 and Forward Camp areas were found to still have hydrocarbon contaminated soils present. Soils stored at the Forward camp location pose a risk to water. Licensee has decided to move soils to Quarry 22 pending construction of the land farm.

FUEL STORAGE:

Waste Oil Storage: None noted at Exploration Camp Owner/Operator: Agnico-Eagle Ltd

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

| | | |
|------------------------|------------------------------------|-----------------------|
| Berms & Liners: A | Water within Berms: NA | Evidence of Leaks: NI |
| Drainage Pipes: A | Pump Station & Catchments Berm: NI | |
| Pipeline Condition: NA | Condition of Tanks: A | |

Comments: The licensee is reminded that any waters accumulated within the Secondary Containment of any fuel storage area must be sampled and the results must be within the license criteria prior to discharge.

SURVEILLANCE NETWORK PROGRAM (SNP)

| | | | |
|--|-----------|------------------------------------|-------------|
| Samples Collected | | Owner /Operator: Agnico-Eagle Ltd. | |
| 0 | | INAC: None | |
| Signs Posted | SNP: None | | Warning: NI |
| Records & Reporting: Sampling results are required | | | |
| Geotechnical Inspection: N/A | | | |

Non-Compliance of Act or Licence: Waste water management on site must be addressed this field season.