

**WATER LICENCE INSPECTION FORM**☒ Original
☐ Follow-Up Report

Licensee	Licensee Representative
Agnico Eagle Mines Ltd.	David Frenette
Licence No. / Expiry	Purpose
2BB-MEA1828/ March 6 th , 2028	Advanced Exploration
Land Authorization No. / Expiry	Project Name
N2016C0003 March 23 rd , 2023	Meadowbank Advanced Exploration Project
Date of Inspection	Inspector
September 9 th , 2022	C. Wilson
Activities Inspected	
<input type="checkbox"/> Camp	<input checked="" type="checkbox"/> Drilling
<input type="checkbox"/> Roads/Hauling	<input type="checkbox"/> Other:
<input type="checkbox"/> Mining	<input type="checkbox"/> Construction
<input type="checkbox"/> Other:	<input type="checkbox"/> Reclamation
	<input type="checkbox"/> Fuel Storage

SECTION 1	<input checked="" type="checkbox"/> Comments (s. __)	<input type="checkbox"/> Non-Compliance with Act or Licence (s. __)	<input type="checkbox"/> Action Required (s. __)
------------------	---	--	---

An inspection of Agnico Eagle Mines Ltd.'s ('Licensee'), Meadowbank Advanced Exploration Project was completed by Crown-Indigenous Relations and Northern Affairs Canada's, Resource Management Officer, Christine Wilson ('Inspector'). The inspection was conducted to ensure compliance with applicable terms and conditions of water licence ('licence') no. 2BB-MEA1828.

PRELIMINARY INFORMATION

- March 26th, 2020 Amendment no. 1 was approved to allow for the relocation of the Amaruq Exploration Camp from Whale Tail Mine Site to N65° 24' 56", W96° 37' 48". The camp has not yet been moved.
- The 2021 annual report is available for review on the Nunavut Water Board ('Board') FTP website in accordance with Part B item 6.
- The Licensee provided an update to the plan titled "Amaruq and GOT Exploration Projects Spill Contingency Plan" for Board approval within 30 days as required by Amendment no. 1, Part H item 1.
- Six (6) drill sites were chosen at random from the information provided in the 2021 annual report.

OBSERVATIONS

1. The following drills holes are inspected and noted to respect licence conditions found in Part F and Part I item 10 with regards to drilling and restoration of drill sites.

Location Name	Land	Notes
7001-21-042 Hole	Crown	No concerns, collar cut off at ground (photo 2).
7001-21-042 Sump	Crown	Well placed, no concerns.
7001-21-052 Hole	Crown	No concerns at the hole but the location has a lot of pooling surface water.
7001-22-066 Hole	Crown	No concerns at the hole (photo 1).
7001-21-023 Hole	Crown	No concerns in area, exact location was never determined (photo 4).
7001-22-072 Hole	IOL	No concerns at hole (photo 5).

2. 100L of diesel was spilled to the ground in a rocky location at approximately N65° 6' 12.78", W96° 17' 23.89". Spill no. 21-388 was assigned to the file. No concerns noted relating to the spill or the remediation (photo 3). The file is recommended for closure-remediated. A spill report and follow-up report is available for review as required by Part H item 5(b) and (c).

SECTION 2	<input type="checkbox"/> Comments (s. __)	<input checked="" type="checkbox"/> Non-Compliance with Act or Licence (s.2)	<input type="checkbox"/> Action Required (s. __)
------------------	--	---	---

Non-compliance related to the terms and conditions of water licence 2BB-MEA1828:

No instances of non-compliance are noted at this time.



SECTION 3

☐ **Comments (s. __)**

☐ **Non-Compliance with Act or Licence, (s. __)**

☒ **Action Required (s.3)**

No actions required.

Licensee or Representative	Inspector's Name
	C. Wilson
Signature	Signature
	<i>Christie Wilson</i>
Date	Date
	October 21 st , 2022

Office Use Only: Follow-up report to be issued by Inspector

☐ Yes ☒ No

cc.: Manager, Licensing, Nunavut Water Board

Manager, Field Operations, Crown Indigenous Relations and Northern Affairs Canada



PHOTO LOG

Date:	Authorization Number:	Camera/Model:	Inspector
September 9th, 2022	2BB-MEA1828	Sony DSC-HX50V Cyber shot	C. Wilson
Photo No.	Lat/Long (DD.MM.SS.SS, NAD83)		
Photo 1	N65° 6' 5.93", W96° 20' 23.45"		



Description:
The vicinity of drill hole 7001-21-066 and surface water accumulation from recent rainfall.




Photo No.

Lat/Long (DD.MM.SS.SS, NAD83)

Photo 2

N65° 6' 11.27", W 96° 17' 21.34"



Description:

Drill Hole 7001-21-042



Photo No.

Lat/Long (DD.MM.SS.SS, NAD83)

Photo 3

N65° 6' 12.78", W 96° 17' 23.89"



Description:

Spill report number 21-388 approximate location. No visible sheen or smell of hydrocarbon.



Photo No.

Lat/Long (DD.MM.SS.SS, NAD83)

Photo 4

N65° 5' 33.08", W 96° 24' 13.09"



Description:

Drill hole 7001-21-023



Photo No.

Photo 5

Lat/Long (DD.MM.SS.SS, NAD83)

N65° 4' 40.78", W 96° 6' 15.27"



Description:

Drill hole 7001-21-072