NWB Annual	Report			Year	being re	ported:	:	2015		
License No:	2BE-MEA1318	3			ed Date: ry Date:	March 7 March 6				
	Project Name	: /	Amaruq, I	Meadowl	oank exp	loration p	rojects	<u> </u>		
	Licensee:	Agnico	Eagle M	ines Ltd						
	Mailing Addre	ess:		r, Quebe	a Mine G	ioldex				
	Name of Com	-	_	-	-	erent from I	Name o	f Licensee	please cla	rify
General Bac	kground Infor	mation	on the Pr	roject (*c	optional):					
Licence Req with	uirements: the		ee must	provide •	the follo	wing info	ormati	on in ac	codance	
	report of water ater; sewage a			-						
wasto mana,	Water Source Water Quantity	` '	1091 3453	135	Quantity Actual Qu Quantity Total Qua Quantity	Allowable uantity Us Allowable antity Use allowable antity Use	ed Do Drillined Drilli total (	mestic (c g (cu.m) ng (cu.m cu.m)	u.m)	
	Waste Manage Solid V Sewage Drill W Greyw Hazare Other: Additional Deta	Waste Disp ge Vaste vater dous		posal						
	Solid Waste All solid wa site for pro attracting v preservative containers fo	stes wer oper dis vildlife. es was	sposal. I Metal v incinera	Domestic vas segn uted. Pla	: waste regated astic an	from the in contai d constr	camp iner fo	o was ir or recyc	icinerate ling. Wo	ed to avoid ood without
	Sewage: Toilet waste effluent rele					er Treati	ment I	Plant "K	odiak Bi	ionest" and
	Greywater: At the Ama treated by th								nd the sl	nowers was
	Drill Waste: Cuttings: T depressions risk of runoj	he drill located								
	<u> Hazardous:</u>									

Hazardous wastes such as used oil, glycol, scrapped fuel, gasoline, batteries were securely packaged. They will be transported to the Meadowbank mine during the winter and ultimately to the boat during the summer. These materials will be transported to a southern facility for disposal respecting regulations.

	uthorized discharges and a summary of follow-up actions taken.	
	Spill No.: 2015-157 (as reported to the Spill Hot-line)	
	Date of Spill: April 19th, 2015	
	Date of Notification to an Inspector: April 19th, 2015	
	Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)	
	A 150 litre Diesel spill occured on the Amaruq winter road. Cleaning of the spill started immediately with an intervention team and spill kits. An excavator was transported to the site to finalize the decontamination and contaminated ice and snow brought to the Meadowbank mine for treatment. Monitoring of the lake was conducted, no residual impacts were noted.	
	Spill No.: Date of Spill: August 6th, 2015 Date of Notification to an Inspector: August 6th, 2015 Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)	
	A 1500 litre Diesel spill occurred at the Amaruq camp site on August 6th, 2015. The spill was stopped, contained and cleaning was started. Before the winter period AEM removed the contaminated soil and stored it temporarily in a berm and installed tarps to avoid contamination of contact water.	
Revisions to	the Spill Contingency Plan	
	Other: (see additional details)	
	Additional Details:	
	An updated version is attached to the annual report, as requested by the Board.	
Revisions to	the Abandonment and Restoration Plan	
Revisions to	othe Abandonment and Restoration Plan  Other: (see additional details)	
Revisions to	Other: (see additional details)	
Revisions to		
	Other: (see additional details)  Additional Details:  An updated version is attached to the annual report, as requested by the Board.	
	Other: (see additional details)  Additional Details:	
	Other: (see additional details)  Additional Details:  An updated version is attached to the annual report, as requested by the Board.  Reclamation Work Undertaken	
Progressive	Additional Details:  An updated version is attached to the annual report, as requested by the Board.  Reclamation Work Undertaken  Additional Details (i.e., work completed and future works proposed)  The drilling casings are removed at the end of the drilling or cut off at ground level if cannot be removed. The casing, in some cases, could be left on a drilling site when the plan is to continue drilling in the existing casing. In such cases, the casing's coordinates are entered in a data base. A final inspection, by a technician, is done when the drilling is completed, to ensure that no remaining waste or materials are present on the site.	
Progressive	Additional Details:  An updated version is attached to the annual report, as requested by the Board.  Reclamation Work Undertaken  Additional Details (i.e., work completed and future works proposed)  The drilling casings are removed at the end of the drilling or cut off at ground level if cannot be removed. The casing, in some cases, could be left on a drilling site when the plan is to continue drilling in the existing casing. In such cases, the casing's coordinates are entered in a data base. A final inspection, by a technician, is done when the drilling is completed, to ensure that no remaining	
Progressive	Additional Details:  An updated version is attached to the annual report, as requested by the Board.  Reclamation Work Undertaken  Additional Details (i.e., work completed and future works proposed)  The drilling casings are removed at the end of the drilling or cut off at ground level if cannot be removed. The casing, in some cases, could be left on a drilling site when the plan is to continue drilling in the existing casing. In such cases, the casing's coordinates are entered in a data base. A final inspection, by a technician, is done when the drilling is completed, to ensure that no remaining waste or materials are present on the site.  The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude)	e) of
Progressive	Additional Details:  An updated version is attached to the annual report, as requested by the Board.  Reclamation Work Undertaken  Additional Details (i.e., work completed and future works proposed)  The drilling casings are removed at the end of the drilling or cut off at ground level if cannot be removed. The casing, in some cases, could be left on a drilling site when the plan is to continue drilling in the existing casing. In such cases, the casing's coordinates are entered in a data base. A final inspection, by a technician, is done when the drilling is completed, to ensure that no remaining waste or materials are present on the site.  The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude each location where sources of water are utilized;	e) of
Progressive	Additional Details:  An updated version is attached to the annual report, as requested by the Board.  Reclamation Work Undertaken  Additional Details (i.e., work completed and future works proposed)  The drilling casings are removed at the end of the drilling or cut off at ground level if cannot be removed. The casing, in some cases, could be left on a drilling site when the plan is to continue drilling in the existing casing. In such cases, the casing's coordinates are entered in a data base. A final inspection, by a technician, is done when the drilling is completed, to ensure that no remaining waste or materials are present on the site.  The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude)	e) of
Progressive	Additional Details:  An updated version is attached to the annual report, as requested by the Board.  Reclamation Work Undertaken  Additional Details (i.e., work completed and future works proposed)  The drilling casings are removed at the end of the drilling or cut off at ground level if cannot be removed. The casing, in some cases, could be left on a drilling site when the plan is to continue drilling in the existing casing. In such cases, the casing's coordinates are entered in a data base. A final inspection, by a technician, is done when the drilling is completed, to ensure that no remaining waste or materials are present on the site.  The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude each location where sources of water are utilized;	e) of

	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;
	Details attached
	Additional Details:
	Results of any additional sampling and/or analysis that was requested by an Inspector
	Additional sampling requested by an Inspector or the Board (See below)
	Additional Details: (date of request, analysis of results, data attached, etc)
	Inspector requested aditionnal monitoring that will be taken next freshet at water crossing located south of the Amaruq camp.
Any other d	etails on water use or waste disposal requested by the Board by November 1 of the year ted.
	No additional sampling requested by an Inspector or the Board
	Additional Details: (Attached or provided below)
Any respons	ses or follow-up actions on inspection/compliance reports
	Inspection and Compliance Report received by the Licensee (Date):
	Additional Details: (Dates of Report, Follow-up by the Licensee)
	Inspections were conducted by AANDC on July 22nd, 2015 and October 29th, 2015
Any addition	nal comments or information for the Roard to consider
,	Within the water licence amendment #3, the Board requests AEM to submit with the 2015 annual report:
	-The Quarry Management Plan; -An updated Waste Management Plan that included the Waste Management plan addendum that has been developed for the drilling on barge; -An updated Spill Contingency Plan that included specifics for dealing with a spill in open water (related to drilling on barge); -An updated reclamation cost estimate.  These documents and the WWTP Management Plan are submitted with this annual report.
Date Submi Submitted/F	Prepared by: David Frenette
	Fax: email: david.frenette@agnicoeagle.com