



## 2019-02-06 AMQ 4 L Engine oil spill

GN reference # : 2019-044

Please find the following information as a follow up to the Spill report submitted February 6<sup>th</sup>, 2019 by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2BB-MEA1318, Part H, Item 5c.

### Spill Description

While the drill SH-47 was operating on the Whale Tail North lake, the motor broke down, engine oil leaked from the vent causing a spill in the secondary containment inside the drill but 4 liters of oil has overflowed the containment and goes on snow.



Spill location: N 65 24'15.62'' W 096 41'53.52''

The event happen on the Whale Tail North where the fish out where done last fall.

### Cause of Spill

The spill has been caused by mechanical issue with the motor.

## Remediation Actions

The drill operators used absorbent pads and shoveled the snow and disposed a contaminated material at the appropriated facility.



## Corrective measures

A routine visual inspection of all system is performed during pre-operations checks as a part of the preventive maintenance program.

## Closure

We trust that the above details described appropriately the spill incident that occurred at the Whale Tail site on February 6<sup>th</sup>, 2019 and the cleanup activities. Please contact the undersigned should you have any questions.

**Martin Archambault**  
**Environmental Senior Coordinator**  
martin.archambault@agnicoeagle.com  
T: 819.759.3555 x6744  
Agnico Eagle Mines Limited  
Meadowbank Division  
Baker Lake, Nunavut, Canada  
X0C 0A0

[agnicoeagle.com](http://agnicoeagle.com)



**AGNICO EAGLE**

