



2022-03-18 WTP 1L Hydraulic Oil

GN reference #: 2022-087

Please find the following information as a follow up to the Spill report submitted March 19, 2022 by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2BB-MEA1828, Part H, Item 5c.

Spill Description

During operations at Whale Tail pit, the dozer operator noticed a stain of hydraulic oil under the winch on the dozer. The dozer was working on Mammoth Lake.



Spill location: 65°24'05.9" 96°43'41.8" on IOL.

The spill occurred on Mammoth Lake.

Cause of Spill

Failed seal on Dozer winch.

Remediation Actions

The dozer operator fixed spill pads to the winch to contain the slow leak of oil and moved the dozer off the Lake. The area was scraped clean and additional spill pads were placed on the ice to collect any residue. Spill pads were brought to the Hazmat storage area.




Corrective measures

The Minex and Orbit Garant drill crew held a stand down meeting regarding spill prevention. Environment will continue toolboxes on spill prevention with all departments.

Closure

We trust that the above details described appropriately the spill incident that occurred at the Meadowbank Complex on March 18, 2022. Please contact the undersigned should you have any questions.



Tom Thomson | Environment Coordinator

tom.thomson@agnicoeagle.com | Direct 819.759.3555 x4606744 |

Agnico Eagle Mines Limited - Meadowbank Division, Suite 540 - Baker Lake, Nunavut, Canada X0C 0A0



agnicoeagle.com

