




Photo 7 9 – 10 July 1998. 2PL outlet channel looking downstream to Tehek Lake.




Photo 8 9 – 10 July 1998. 2PL outlet channel looking upstream from Tehek Lake.




Photo 9 9 – 10 July 1998. 2PL tributary inflow from north, looking south towards 2PL.




Photo 10 9 – 10 July 1998. Drilltrial Lake outlet channel to 2PL, looking northeast to Drilltrail Lake.




Photo 11 9-10 July 1998. Tern Lake outlet channel to Drilltrail Lake, looking east.



Photo 12 20 June 2002. 3PL west outlet channel at measurement section. Note anchor ice and snow/ice in channel along left bank.




Photo 13 20 June 2002. 3PL east channel outlet channel looking WNW. Discharge measurement in progress.



Photo 14 20 June 2002. 2PL outlet channel looking northeast. Discharge measurement in progress. Note ice in channel along both banks.