



WATER LICENCE INSPECTION FORM

☒ Original
☐ Follow-Up Report

Licensee	Licensee Representative
2BB-MEL1424	Mario Bolduc
Licence No. / Expiry	Representative's Title
July 21st, 2024	P.Geo
Land / Other Authorizations	Land / Other Authorizations
IOL	--
Date of Inspection	Inspector
June 8th 2018	WRO C. Wilson
Activities Inspected	
<input type="checkbox"/> Camp	<input checked="" type="checkbox"/> Drilling
<input type="checkbox"/> Roads/Hauling	<input type="checkbox"/> Mining
	<input type="checkbox"/> Construction
	<input type="checkbox"/> Reclamation
	<input type="checkbox"/> Fuel Storage
	<input checked="" type="checkbox"/> Other: Water Supply
	<input type="checkbox"/> Other:

SECTION 1	<input checked="" type="checkbox"/> Comments (s.1)	<input type="checkbox"/> Non-Compliance with Act or Licence (s.__)	<input type="checkbox"/> Action Required (s.__)
<p>On June 8th, 2018 an inspection was conducted of Agnico Eagle Mines’ (‘AEM’), spring drilling campaign, authorized under water licence no. 2BB-MEL1424. The inspection was completed by Indigenous and Northern Affairs Canada’s Water Resource Officer, Christine Wilson and Atuat Shouldice with the assistances of the Government of Nunavut’s Conversation Officer, Daniel Kaludjak.</p> <p>This report was produced with the findings of the inspection. Note: the inspection plan included an additional three location that were aborted.</p> <p><i>Observations</i></p> <ol style="list-style-type: none">Drill hole M18-2464 is located approximately at N63° 00’ 06.4”, W92° 09’ 30.4, which is on Inuit owned land with surface and sub surface rights. The drill rig had recently moved to this location and begun drilling.The drill site is located in between two small water bodies, with the actually drill approximately 60ft from a flowing stream (photo 1). The inspector is concerned that the proponent may have failed to meet the requirements of PART F item 1.The water intake is located on a lake proximal to the drill hole, approximately at N63° 00’ 12.3”, W92° 10’ 01.6”. The water intake is operated in accordance with PART C item 1, item 3 and item 5.The cuttings line is located on to the north east side of the drill rig. Though the location of the line appeared to be 31 meters from a water body, the cuttings water would have connectivity with the nearby lake because of freshet. This activity fails to meet the requirements of PART F item 2.			
SECTION 2	<input type="checkbox"/> Comments (s.__)	<input checked="" type="checkbox"/> Non-Compliance with Act or Licence (s.2)	<input type="checkbox"/> Action Required (s.__)
<p>Non-compliance or concerns related to water licence no. 2BB-MEL1424;</p> <ul style="list-style-type: none">PART F item 1, concern with respecting the thirty-one (31) meter boundary from a water body.PART F item 2, failure to dispose drill water at a location where direct flow into a water body is not possible. <p>Non-compliance related to the <i>Nunavut Waters and Nunavut Surface Rights Tribunal Act S.C 2002, c. 10</i> ;</p> <ul style="list-style-type: none">Section 90(1), failure to comply with the terms of water licence no. 2BB-MEL1424.			
SECTION 3	<input type="checkbox"/> Comments (s.__)	<input type="checkbox"/> Non-Compliance with Act or Licence, (s.__)	<input checked="" type="checkbox"/> Action Required (s.3)
<p><i>Actions Required</i></p> <p>-AEM will provide a response to the inspector regarding the two recent failures to comply, PART F item 1 and item 2. The response must include a brief summary (‘cheat sheet’) of the terms and conditions of the water licence which apply during the drilling process (e.g.: prior to set up, during drilling and closure.)</p> <p>-AEM will provide this sheet to the drill contractor, AEM Meliadine Environment Department and the inspector prior to July 6th.</p> <p><i>Closing Remarks</i></p> <p>-The inspector noted that this would be the second failure to comply related to drilling.</p>			

Licensee or Representative	Inspector's Name
	WRO C Wilson
Signature	Signature
	<i>Original signed on file</i>
Date	Date
	June 13 th , 2018

Office Use Only:	Follow-up report to be issued by Inspector	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
------------------	--	---

cc. Erik Allain, Director, Lands Administration, INAC
Manager, Licensing, Nunavut Water Board
David Frenette, Environmental Coordinator, AEM
Mario Bolduc, Project Geologist, AEM

Attached: Photo Log, June 8th, 2010





PHOTO LOG

Date:	Authorization Number:	Camera/Model:	Inspector
June 8th, 2018	2BB-MEL1424	Sony DSC-HX50V Cyber shot	WRO Wilson
Photo No.		Lat/Long (DD.MM.SS.SS, NAD83)	
Photo 1		N63° 00' 6.46", W92° 9' 29.78"	



Description:
Mid frame: flowing stream between to lakes.