



Photo 1 A functioning culvert crossing.



Photo 2 Typical roadbed conditions.



Photo 3 A washed out barrel culvert bypassed by a new channel.



Photo 4 A typical small crossing.



Photo 5 A typical medium sized crossing.



Photo 6 A major watercourse along the road.

			
MARY RIVER PROJECT - BULK SAMPLING PROGRAM			
EXISTING ROAD CONDITIONS			
	P/A NO. NB102-00181/6	REF. 1	REV. 0
	FIGURE 2.13		