

WATER USE INSPECTION REPORT

Date: July 14,2009	Licensee Rep. (Name/Title): Jim Mallard
Licensee: Baffinland Iron Mines	Licence No.: 2BB-MRY0810- (Steensby inlet)

WATER SUPPLY

Source(s): None – Camp inactive at present	Quantity used: None
Owner:/Operator: Baffinland Iron Mines	

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

Intake Facilities: NA	Storage Structure: NA	Treatment Systems: NA	Chemical Storage: NA
Flow Meas. Device: NA	Conveyance Lines: NA	Pumping Stations: NA	Screen : NA

**Comments:** Camp is inactive at this time. No water consumption. Equipment to pump at treat water are stored on site for when and if Camp is reactivated.

WASTE DISPOSAL

**Sewage:** Sewage Treatment System (Prim./Sec/Ter.): N/A

Natural Water Body: No	Continuous Discharge (land or water): None		
Seasonal Discharge: None	Wetlands Treatment: None	Trench: None	

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

Discharge Quality: NI	Decant Structure: NA	Erosion: None
Discharge Meas. Device: NA	Dyke Inspection: NI	Seepages: None
Dams, Dykes: A	Freeboard: NA	Spills: None
Construction: NI	O&M Plan: A	A&R Plan: A
Discharge: None	Effluent Discharge Rate: Unknown	

**Comments:** No human wastes generated at Steensby Inlet at this time.

**Solid Waste:** No wastes were noted on site at the time of Inspection

**Owner/Operator:** Environment Canada & National Defence

Landfill: None	Burn & Landfill: NA	Other: (Barrels)
----------------	---------------------	------------------

**Comments:** No waste is currently generated on site. Wastes have been hauled back to Mary River.

FUEL STORAGE: Barrel storage

**Waste Oil Storage:** None **Owner/Operator:** Baffinland Iron mines

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

Berms & Liners: A	Water within Berms: U	Evidence of Leaks: None
Drainage Pipes: None	Pump Station & Catchments Berm: NA	
Pipeline Condition: NA	Condition of Tanks: NA	

**Comments:** 7000 drums are currently stored on site. Barrels are on secondary Containment and stored over 30 M from water. Water has built up in the secondary containment and must be removed. No signs of leakage were noted during the Inspection.

SURVEILLANCE NETWORK PROGRAM (SNP)

Samples Collected : 0		Owner /Operator: Monthly reports are to be provided when Camp is reactivated.
0		INAC: No water use or waste was noted on site.
Signs Posted	SNP: None	Warning: None
Records & Reporting: records to be provided in annual report		
Geotechnical Inspection: N/A		

**Non-Compliance of Act or Licence:** The Steensby inlet site is working in compliance with the terms and conditions of the License at the time of the inspection. It is highly recommended that the current frequency of inspections on the fuel cache is maintained and as the summer progresses Inspections are made more frequently.

A.Keim

Inspector’s Name

Sent by E-mail

Inspector’s Signature