



## September 30, 2018 WTP Road

GN reference # : 2018-408

Please find the following information as a follow up to the Spill report submitted September 30<sup>th</sup>, 2018 by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2BC-WTP1819, Part G, Item 5c.

### Spill Description

During operations at Quarry 35 along WTP road, a loose solenoid on the hydraulic pump caused oil to spill on the ground.

Spill location: Easting 65'14'06" 96'24'47"

There were no off site impact or discharge to any receiving watercourses. The distance to the closest lake is estimated at 200 meters.



### Cause of Spill

A solenoid on the hydraulic system pump of a loader working at Quarry 35 along the WTP road came loose causing hydraulic oil to spill on the ground.

## Remediation Actions

The equipment was immediately stopped. Absorbent pads were laid out to contain the spill on the ground. Once the truck was fixed and moved out of the area, the ground was scrapped clean and contaminated material was brought to the Meadowbank Landfarm area.



## Corrective measures

Regular pre-operation checks are completed on equipment also including visual inspection of the hydraulic systems.

## Closure

We trust that the above details described appropriately the spill incident that occurred at the Meadowbank on September 30<sup>th</sup>, 2018 and the cleanup activities. Please contact the undersigned should you have any questions.



**Tom Thomson** | Environmental Coordinator

tom.thomson@agnicoeagle.com | Direct 819.759.3555 x6744

Agnico Eagle Mines Limited - Meadowbank Division, Suite 540 - Baker Lake, Nunavut, Canada  
XOC 0A0

[agnicoeagle.com](http://agnicoeagle.com)

