



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR June 23 2014		REPORT TIME 3:00 pm		<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT	REPORT NUMBER 14 -234
B	OCCURRENCE DATE: MONTH – DAY – YEAR Spring 2014		OCCURRENCE TIME Undetermined			
C	LAND USE PERMIT NUMBER (IF APPLICABLE) N2012C0030			WATER LICENCE NUMBER (IF APPLICABLE) 2BE-ANG1318		
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION Nutaaq Camp, Angilak Property, NU				REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN	
E	LATITUDE DEGREES 62 MINUTES 34 SECONDS 17			LONGITUDE DEGREES 98 MINUTES 27 SECONDS 21		
F	RESPONSIBLE PARTY OR VESSEL NAME Kivalliq Energy Corporation		RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION 1020 800 West Pender Street			
G	ANY CONTRACTOR INVOLVED None		CONTRACTOR ADDRESS OR OFFICE LOCATION			
H	PRODUCT SPILLED P50		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 1/2 drum (100 litres estimate)		U.N. NUMBER 1202	
	SECOND PRODUCT SPILLED (IF APPLICABLE)		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES		U.N. NUMBER	
I	SPILL SOURCE 205 litre Drum		SPILL CAUSE Broken Valve from Tipped Drum		AREA OF CONTAMINATION IN SQUARE METRES 1 square metre	
J	FACTORS AFFECTING SPILL OR RECOVERY Remote Location		DESCRIBE ANY ASSISTANCE REQUIRED		HAZARDS TO PERSONS, PROPERTY OR ENVIRONMENT None	
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS The Nutaaq camp at the Angilak property is a remote tent camp, 225 km southwest of Baker Lake, NU. The camp comprises temporary plywood buildings and twelve 14x16 vinyl WeatherPort tents on plywood floors situated on a flat top sand esker approx 8 metres above the surrounding tundra. The nearest water body Nutaaq Lake is approx. 200 metres west of the spill site. 2 workers sent to inspect the site on the weekend noted that tent W5 was lifted off its foundations by wind and moved 4 metres south. An adjacent fuel drum was knocked over. The impact cracked a fuel valve connection at the drum causing a fuel leak. A surface stain of approximately 1 sq. metre is noted. The spill did not enter any water body or drainage. Contaminated soils were excavated to a depth of approx. 1 metre by the workers using shovels. The contaminated soil has been contained in four 205 litre drums. The drums will be removed from site and disposed of at an authorized facility. Photo's are attached.					
L	REPORTED TO SPILL LINE BY Bill Cronk	POSITION Exploration Manager	EMPLOYER Kivalliq Energy Corp	LOCATION CALLING FROM Nutaaq Camp	TELEPHONE 604-759-4750	
M	ANY ALTERNATE CONTACT Maria Egerton	POSITION Permitting	EMPLOYER Kivalliq Energy Corp	ALTERNATE CONTACT Vancouver	ALTERNATE TELEPHONE 604-646-4527	
REPORT LINE USE ONLY						
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130	
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED	
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS		
LEAD AGENCY						
FIRST SUPPORT AGENCY						
SECOND SUPPORT AGENCY						
THIRD SUPPORT AGENCY						

Kivalliq Energy Corp.
Photo Document to accompany June 23, 2014 NU Spill Report



Photo 1: Tent W5 Shifted 4m South From Tent Footings (note: Nutaag Lake 200m West)



Photo 2: Spill Location and Excavated Pit



Photo 3: Excavated Pit behind Tent W5 & Toppled Tent Footings



Photo 4: Broken Valve on Fuel Drum